

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24070025/EMA3Q2**Date:** 14/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747\_03  
**Claimant Vehicle No :** SME2603S **Insured Vehicle No :** SNJ2129G  
Date of Loss: 29/06/2024 Nature of Claim: TP Claim No: MFL2024D0007571

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SME2603S**  
Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGJH703395  
Reg. Date: 31/10/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5013334  
Colour: White Odometer: 58656 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,291.00	1,020.00	1,271.00	55.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	1,630.00	3,280.00	66.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,201.00</b>	<b>2,650.00</b>	<b>4,551.00</b>	<b>63.20</b>
<b>+ GST 9.00/9.00% (S\$)</b>	648.09	238.50	409.59	63.20
<b>Nett Amount (S\$)</b>	<b>7,849.09</b>	<b>2,888.50</b>	<b>4,960.59</b>	<b>63.20</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 9.00% GST) (S\$)</b>		327.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>3,242.75</b>		

**INSPECTION**

Date of Assignment: 03/07/2024  
Date Inspected: 03/07/2024 Inspected At: CYCLE & CARRIAGE KIA PTE LTD (HQ)  
330 UBI ROAD 3  
Singapore 408650  
Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2024)
Parts:	143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME2603S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Deformed	749.00 FS	*749.00 FS
3	1		*COVER -RR BUMPER LWR	Cut	241.00 FS	*241.00 FS
4	10		*CLIP BUMPER	Necessary	10.00 FS	*10.00 FS
5	1		*BRACKET ASSY -RR BPR SIDE UPR	Not Necessary	25.00 FS	*- FS
6	1		*BRACKET ASSY -RR BPR SIDE UPR R	Not Necessary	31.00 FS	*- FS
7	1		*COVER RR BUMPER FOG LAMP LH	Not Necessary	23.00 FS	*- FS
8	1		*COVER RR BUMPER FOG LAMP RH	Not Necessary	23.00 FS	*- FS
9	1		*LAMP ASSY -SIDE T/SIGNAL LH	Not Necessary	201.00 FS	*- FS
10	1		*LAMP ASSY -SIDE T/SIGNAL RH	Not Necessary	201.00 FS	*- FS
11	1		*EXTN WIRING ASSY -BWS	Not Necessary	207.00 FS	*- FS
12	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	46.00 FS	*- FS
13	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
14	1		*BRACKET -RR BEAM UPR MTG ,LH	Not Necessary	9.00 FS	*- FS
15	1		*BRACKET -RR BEAM UPR MTG ,LH	Not Necessary	9.00 FS	*- FS
16	1		*BRACKET -RR BEAM LWR ,CTR	Not Necessary	6.00 FS	*- FS
17	2		*BRACKET -RR BEAM LWR MTG	Not Necessary	12.00 FS	*- FS
18	1		*STAY -RR BUMPER LH	Not Necessary	65.00 FS	*- FS
19	1		*STAY -RR BUMPER RH	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,291.00	1,020.00
-------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CARRY OUT DIAGNOSTIC CHECK ON KDS AND CLEAR TROUBLE CODE	New	280.00	280.00
2	TO CHECK WIRING AND ELECTRICAL SYSTEM	New	100.00	80.00
3	TO REMOVE & REINSTALL FLOOR BOARDS ,CARPETS & TRIMS TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	0.00
4	TO REPLACE UPR & LWR REAR BUMPER ,BUMPER CLIPS ,SIDE BRACKETS,SIGNAL LAMPS & COVERS EXTN WIRING ANTENNA BEAM & BRACKETS STAYS ,ETC TO REPAIR REAR END PANEL STRAIGHTEN REFORM ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	1,920.00	640.00
5	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (UPPER REAR BUMPER & REAR END PANEL)	New	1,650.00	550.00
6	TO CHECK ,TEST & REFIT REVERSE SENSORS	New	100.00	80.00
7	TO SUPPLY ONE SET REVERSE SENSOR	New	220.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,910.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >