

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24120277/ENP3E2**Date:** 14/01/2025REFERENCE

Insured/Claimant:	RENOLA MANUFACTURING PTE LTD	Policy No:	MCV24A00007700
Date of Loss:	29/11/2024	Nature of Claim:	OD
		Claim No:	DMCV2400277H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN6032Z	Engine No:	4P10B28967
Make & Model:	mitsubishi canter, 3.0 D (M)	Chassis No:	FEB21EA00818
Reg. Date:	27/08/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,550.25	16,905.00	14,645.25	46.42
Miscellaneous Items	70.00	70.00	0.00	0.00
Labour	3,450.00	1,880.00	1,570.00	45.51
Paintwork Labour	1,800.00	800.00	1,000.00	55.56
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	36,870.25	19,655.00	17,215.25	46.69
Approved Total (Overridden) (\$\$)		14,000.00		
- Excess (\$\$)	600.00	1,600.00	-1,000.00	-166.67
(\$\$)	36,270.25	12,400.00	23,870.25	65.81
+ GST 9.00/9.00% (\$\$)	3,264.32	1,116.00	2,148.32	65.81
Nett Amount (\$\$)	39,534.57	13,516.00	26,018.57	65.81

INSPECTION

Date of Assignment:	18/12/2024	Present Location:	Kan Fook Sing Motor Workshop (Defu)
Date Inspected:	20/12/2024	Inspected At:	Kan Fook Sing Motor Workshop (Defu) Blk 8 Defu South Street 1, Defu Industrial City #04-29 Singapore 533758
Estimated Period of Repair:	10.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jan 2025)	
Parts:	N/A	mitsubishi canter 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN6032Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS (WCP)	Broken	750.00 F	*750.00 F
2	1		*FRONT WINDSCREEN RUBBER (WCP)	Cut	280.00 F	*280.00 F
3	1		*FRONT WINDSCREEN PILLAR RH (WCP)	Repair	1,250.00 F	*- F
4	1		*DASHBOARD (WCP)	Deformed	1,450.00 F	*1,450.00 F
5	1		*DASHBOARD REINFORCEMENT (WCP)	Bent	950.00 F	*950.00 F
6	1		*DASHBOARD LOWER COVER LH (WCP)	Broken	450.00 F	*450.00 F
7	1		*FRONT CORNER PANEL RH (WCP)	Missing	350.00 F	*350.00 F
8	1		*FRONT CORNER PANEL LH (WCP)	Broken	350.00 F	*350.00 F
9	1		*FRONT WIPER PANEL (WCP)	Broken	380.00 F	*380.00 F
10	1		*FRONT WIPER ARM RH (WCP)	Bent	95.00 F	*95.00 F
11	1		*FRONT WIPER ARM LH (WCP)	Bent	95.00 F	*95.00 F
12	1		*FRONT WIPER BLADE RH (WCP)	Cut	75.00 F	*75.00 F
13	1		*FRONT WIPER BLADE LH (WCP)	Cut	75.00 F	*75.00 F
14	1		*FRONT WIPER CAP RH (WCP)	Broken	10.00 F	*10.00 F
15	1		*FRONT WIPER CAP LH (WCP)	Missing	10.00 F	*10.00 F
16	1		*FRONT WIPER NOZZLE RH (WCP)	Not Necessary	75.00 F	*- F
17	1		*FRONT WIPER NOZZLE LH (WCP)	Not Necessary	75.00 F	*- F
18	1		*FRONT WIPER LINKAGE (WCP)	Bent	220.00 F	*220.00 F
19	1		*FRONT WIPER LINKAGE MOTOR (WCP)	Jammed	390.00 F	*390.00 F
20	1		*FRONT PANEL (WCP)	Dented	1,000.00 F	*1,000.00 F
21	1		*FRONT PANEL FUSO EMBLEM (WCP)	Necessary	100.00 F	*100.00 F
22	1		*FRONT GRILLE (WCP)	Missing	680.00 F	*680.00 F
23	1		*FRONT GRILLE EMBLEM (WCP)	Missing	65.00 F	*65.00 F
24	1		*FRONT GRILLE CANTER EMBLEM (WCP)	Missing	65.00 F	*65.00 F
25	1		*FRONT GRILLE BRACKET (WCP)	Missing	105.00 F	*105.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	10		*FRONT GRILLE CLIP (WCP)	Necessary	35.00 F	*35.00 F
27	1		*FRONT HEADLAMP RH (WCP)	Not Necessary	380.00 F	*- F
28	1		*FRONT HEADLAMP LH (WCP)	Not Necessary	380.00 F	*- F
29	1		*FRONT HEADLAMP LOWER RUBBER RH (WCP)	Not Necessary	35.00 F	*- F
30	1		*FRONT HEADLAMP LOWER RUBBER LH (WCP)	Not Necessary	35.00 F	*- F
31	1		*FRONT SIGALLAMP RH (WCP)	Not Necessary	260.00 F	*- F
32	1		*FRONT SIGALLAMP LH (WCP)	Not Necessary	260.00 F	*- F
33	1		*FRONT SIDE LAMP RH (WCP)	Not Necessary	210.00 F	*- F
34	1		*FRONT SIDE LAMP LH (WCP)	Not Necessary	210.00 F	*- F
35	1		*FRONT BUMPER (WCP)	Dented	750.00 F	*750.00 F
36	1		*FRONT BUMPER SIDE RUBBER RH (WCP)	Cut	280.00 F	*280.00 F
37	1		*FRONT BUMPER SIDE RUBBER LH (WCP)	Cut	280.00 F	*280.00 F
38	1		*FRONT BUMPER BRACKET RH (WCP)	Bent	155.00 F	*155.00 F
39	1		*FRONT BUMPER BRACKET LH (WCP)	Bent	155.00 F	*155.00 F
40	1		*FRONT BUMPER INNER BRACKET RH (WCP)	Not Necessary	135.00 F	*- F
41	1		*FRONT BUMPER INNER BRACKET LH (WCP)	Not Necessary	135.00 F	*- F
42	1		*FRONT BUMPER CROSS MEMBER (WCP)	Not Necessary	300.00 F	*- F
43	1		*FRONT HORN (WCP)	Not Necessary	85.00 F	*- F
44	1		*AIR CON BLOWER (WCP)	Broken	2,350.00 F	*2,350.00 F
45	1		*HEATER UNIT (WCP)	Broken	750.00 F	*750.00 F
46	1		*RADIATOR (WCP)	Not Necessary	980.00 F	*- F
47	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	300.00 F	*- F
48	1		*RADIATOR FAN (WCP)	Not Necessary	320.00 F	*- F
49	1		*RADIATOR FAN CLUTCH (WCP)	Not Necessary	450.00 F	*- F
50	1		*FRONT CABIN BAR (WCP)	Not Necessary	650.00 F	*- F
51	1		*FRONT CABIN BAR SEAL RH (WCP)	Not Necessary	115.00 F	*- F
52	1		*FRONT CABIN BAR SEAL LH (WCP)	Not Necessary	115.00 F	*- F
53	1		*FRONT CABIN BAR BRACKET RH (WCP)	Not Necessary	450.00 F	*- F
54	1		*FRONT CABIN BAR BRACKET LH (WCP)	Not Necessary	450.00 F	*- F
55	1		*FRONT CABIN BAR SHAFT (WCP)	Not Necessary	550.00 F	*- F
56	1		*REAR CABIN BAR (WCP)	Not Necessary	520.00 F	*- F
57	1		*REAR CABIN LOCK RH (WCP)	Not Necessary	230.00 F	*- F
58	1		*REAR CABIN LOCK LH (WCP)	Not Necessary	230.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*EAR CABIN LOCL LEVER RH (WCP)	Not Necessary	150.00 F	*- F
60	1		*EAR CABIN LOCL LEVER LH (WCP)	Not Necessary	150.00 F	*- F
61	1		*BRAKE BOOSTER PUMP (WCP)	Dented	2,000.00 F	*2,000.00 F
62	1		*BRAKE MASTER PUMP (WCP)	Not Necessary	1,800.00 F	*- F
63	1		*AIR CON CONDENSER (WCP)	Not Necessary	650.00 F	*- F
64	1		*AIR CON FAN ASSY (WCP)	Not Necessary	650.00 F	*- F
65	1		*AIR CON FAN BRACKET (WCP)	Not Necessary	150.00 F	*- F

F=Franchise part.

Sub Total (S\$)	27,435.00	14,700.00
+ Margin on L,N Items 15.00/15.00% (S\$)	4,115.25	2,205.00
Total Parts (S\$)	31,550.25	16,905.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ERP STICKER (NECESSARY)	20.00	20.00
2	1	FRONT NUMBER PLATE (CUT)	50.00	50.00
Sub Total (\$\$)			70.00	70.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	1,800.00	800.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	100.00	30.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	100.00
4	TO REMOVE/REFIT DASHBOARD	New	240.00	150.00
5	TO REMOVE/REFIT AIR CON BLOWER AND REFILL AIR CON GAS	New	180.00	120.00
6	TO REMOVE/REFIT ROOF LINING,CUSHION AND CARFPET ETC	New	180.00	80.00
7	TO REMOVE/REFIT CABIN HEAD	New	450.00	400.00
8	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FTING NEW PARTS	New	2,200.00	1,000.00
Gross Labour Cost (\$\$)			5,250.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >