



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCV24A00007700	Date of Loss:	29/11/2024
Vehicle Reg. No.:	YN6032Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RENOLA MANUFACTURING PTE LTD		
Make/Model:	MITSUBISHI CANTER, 3.0 D (M)	Vehicle Reg. Date:	27/08/2014
Vehicle Colour:	WHITE	Chassis No:	FEB21EA00818
Engine No:	4P10B28967		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	31,550.25
Miscellaneous Items	70.00
Labour	3,450.00
Paintwork Labour	1,800.00
Towing	0.00
Calculated Gross Total (S\$)	36,870.25
- Excess (S\$)	600.00
(S\$)	36,270.25
+ GST 9.00% (S\$)	3,264.32
Nett Amount (S\$)	39,534.57

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Dec 2024)

Parts: N/A MITSUBISHI CANTER 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/YN6032Z/16/12/2024 15:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS / BR	0.00	0.00	*750.00 F ✓
2	1		*FRONT WINDSCREEN RUBBER / CVI	0.00	0.00	*280.00 F ✓
3	1		*FRONT WINDSCREEN PILLAR RH x R	0.00	0.00	*1,250.00 F ✗
4	1		*DASHBOARD ? / DEF	0.00	0.00	*1,450.00 F /
5	1		*DASHBOARD REINFORCEMENT ? / BT	0.00	0.00	*950.00 F /
6	1		*DASHBOARD LOWER COVER LH ? / BR	0.00	0.00	*450.00 F /
7	1		*FRONT CORNER PANEL RH / mis	0.00	0.00	*350.00 F ✓
8	1		*FRONT CORNER PANEL LH / BR	0.00	0.00	*350.00 F ✓
9	1		*FRONT WIPER PANEL / BR	0.00	0.00	*380.00 F ✓
10	1		*FRONT WIPER ARM RH / BT	0.00	0.00	*95.00 F ✓
11	1		*FRONT WIPER ARM LH / BT	0.00	0.00	*95.00 F ✓
12	1		*FRONT WIPER BLADE RH / CVI	0.00	0.00	*75.00 F ✓
13	1		*FRONT WIPER BLADE LH / CVI	0.00	0.00	*75.00 F ✓
14	1		*FRONT WIPER CAP RH / BR mis	0.00	0.00	*10.00 F ✓
15	1		*FRONT WIPER CAP LH / mis	0.00	0.00	*10.00 F ✓
16	1		*FRONT WIPER NOZZLE RH x nn	0.00	0.00	*75.00 F ✗
17	1		*FRONT WIPER NOZZLE LH x nn	0.00	0.00	*75.00 F ✗
18	1		*FRONT WIPER LINKAGE ? / BT	0.00	0.00	*220.00 F /
19	1		*FRONT WIPER LINKAGE MOTOR ? / Jammed	0.00	0.00	*390.00 F /
20	1		*FRONT PANEL / DD	0.00	0.00	*1,000.00 F ✓
21	1		*FRONT PANEL FUSO EMBLEM / MC	0.00	0.00	*100.00 F ✓
22	1		*FRONT GRILLE / mis	0.00	0.00	*680.00 F ✓
23	1		*FRONT GRILLE EMBLEM / mis	0.00	0.00	*65.00 F ✓
24	1		*FRONT GRILLE CANTER EMBLEM / mis	0.00	0.00	*65.00 F ✓
25	1		*FRONT GRILLE BRACKET / mis	0.00	0.00	*105.00 F ✓
26	10		*FRONT GRILLE CLIP / MC	0.00	0.00	*35.00 F ✓
27	1		*FRONT HEADLAMP RH ? x nn	0.00	0.00	*380.00 F ✓
28	1		*FRONT HEADLAMP LH ? x nn	0.00	0.00	*380.00 F ✓
29	1		*FRONT HEADLAMP LOWER RUBBER RH x nn	0.00	0.00	*35.00 F ✗
30	1		*FRONT HEADLAMP LOWER RUBBER LH x nn	0.00	0.00	*35.00 F ✗
31	1		*FRONT SIGALLAMP RH ? x nn	0.00	0.00	*260.00 F ✓
32	1		*FRONT SIGALLAMP LH ? x nn	0.00	0.00	*260.00 F ✓
33	1		*FRONT SIDE LAMP RH x nn	0.00	0.00	*210.00 F ✗
34	1		*FRONT SIDE LAMP LH x nn	0.00	0.00	*210.00 F ✗
35	1		*FRONT BUMPER / DD	0.00	0.00	*750.00 F ✓
36	1		*FRONT BUMPER SIDE RUBBER RH / CVI	0.00	0.00	*280.00 F ✓
37	1		*FRONT BUMPER SIDE RUBBER LH / CVI	0.00	0.00	*280.00 F ✓
38	1		*FRONT BUMPER BRACKET RH ? / BT	0.00	0.00	*155.00 F /
39	1		*FRONT BUMPER BRACKET LH ? / BT	0.00	0.00	*155.00 F /
40	1		*FRONT BUMPER INNER BRACKET RH ? x nn	0.00	0.00	*135.00 F ✓
41	1		*FRONT BUMPER INNER BRACKET LH ? x nn	0.00	0.00	*135.00 F ✓
42	1		*FRONT BUMPER CROSS MEMBER ? x nn	0.00	0.00	*300.00 F ✓
43	1		*FRONT HORN x nn	0.00	0.00	*85.00 F ✗
44	1		*AIR CON BLOWER ? / BR	0.00	0.00	*2,350.00 F /
45	1		*HEATER UNIT ? / BR	0.00	0.00	*750.00 F /

Kan Fook Sing Motor Workshop/YN6032Z/16/12/2024 15:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*RADIATOR x nn	0.00	0.00	*980.00 F
47	1		*RADIATOR FAN COWLING x nn	0.00	0.00	*300.00 F
48	1		*RADIATOR FAN x nn	0.00	0.00	*320.00 F
49	1		*RADIATOR FAN CLUTCH x nn	0.00	0.00	*450.00 F
50	1		*FRONT CABIN BAR x nn	0.00	0.00	*650.00 F
51	1		*FRONT CABIN BAR SEAL RH x nn	0.00	0.00	*115.00 F
52	1		*FRONT CABIN BAR SEAL LH x nn	0.00	0.00	*115.00 F
53	1		*FRONT CABIN BAR BRACKET RH x nn	0.00	0.00	*450.00 F
54	1		*FRONT CABIN BAR BRACKET LH x nn	0.00	0.00	*450.00 F
55	1		*FRONT CABIN BAR SHAFT x nn	0.00	0.00	*550.00 F
56	1		*REAR CABIN BAR x nn	0.00	0.00	*520.00 F
57	1		*REAR CABIN LOCK RH x nn	0.00	0.00	*230.00 F
58	1		*REAR CABIN LOCK LH x nn	0.00	0.00	*230.00 F
59	1		*EAR CABIN LOCL LEVER RH x nn	0.00	0.00	*150.00 F
60	1		*EAR CABIN LOCL LEVER LH x nn	0.00	0.00	*150.00 F
61	1		*BRAKE BOOSTER PUMP / DD	0.00	0.00	*2,000.00 F /
62	1		*BRAKE MASTER PUMP x nn	0.00	0.00	*1,800.00 F
63	1		*AIR CON CONDENSER x nn	0.00	0.00	*650.00 F
64	1		*AIR CON FAN ASSY x nn	0.00	0.00	*650.00 F
65	1		*AIR CON FAN BRACKET x nn	0.00	0.00	*150.00 F

F=Franchise part.

Sub Total (\$\$)	27,435.00
+ Margin on L,N Items 15.00% (\$\$)	4,115.25
Total Parts (\$\$)	31,550.25

Kan Fook Sing Motor Workshop/YN6032Z/16/12/2024 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

14,700.00
+15%
16,905.00

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ERP STICKER	20.00
2	1	FRONT NUMBER PLATE	50.00
Sub Total (S\$)			70.00 /

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New 800	1,800.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New 30	100.00
3	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00
4	TO REMOVE/REFIT DASHBOARD	New 150	240.00
5	TO REMOVE/REFIT AIR CON BLOWER AND REFILL AIR CON GAS	New 120	180.00
6	TO REMOVE/REFIT ROOF LINING,CUSHION AND CARPET ETC	New 80	180.00
7	TO REMOVE/REFIT CABIN HEAD	New 400	450.00
8	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FTING NEW PARTS	New 1000	2,200.00
2680			
Gross Labour Cost (S\$)			5,250.00

Kan Fook Sing Motor Workshop/YN6032Z/16/12/2024 15:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

19,655.00

20/12/24, 2:00pm

L/S - 15,724.00

OD - M AL

EX 11-?

Repair limit \$14k

LP

✓ R Sy

10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: