

ASS. REC. BY: NAZ

REF:

FCI

DD

PIF

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: GBM 3682 U

at Workshop m/s EFFICIENT MOTOR

of 37 LOYANG WAY S (508734)

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Veh No: GBM 3682 U

Yr Regn: 1.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SHINERAY X30LEV V2.0 cc

Colour: WHITE

Sp. Reading: 10,544

Eng/No: _____

C/No: LM6CKD2XXPX002346

Gen. Cond: Good / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or

Brake: (Inorder) / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / (STD) / Rim or

Tyre Size: F: 175/70 R14 LT

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FARROAD

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 16/12/2024

Survey held at

Des. of Damages: Fnt / Rear / (O/S) / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 19/12/2024

The U/C / Chassis frame / Body Structure affected due to collision.

FCI PIF