

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401972

INV Date : 24-12-2024

Reference CS3/SMR24120291/Knp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. FBR 6231S
Insured Veh. SMB 1390C
Claim No. BUS/12/24/5028
Policy No.
Accident Date 15/12/2024
Inspection Date 19/12/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.		Ref:	CS3/SMR24120291/Knp3m4	
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE		Date:	24/12/2024	
757705		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SMB 1390C	Veh. Inspected	FBR 6231S	
Policy No.	-	Coverage	0	
Claim No.	BUS/12/24/5028	Excess	\$0.00	
Assign From	HUA YEN	Assign Date	19/12/2024	
2. Vehicle Details				
Make & Model	YAMAHA AEROX	C.C	155	
Engine No.	G3J8E0144168	Year of Reg.	01/09/2020	
Chassis No.	MH3SG4640LJ070352	Colour	BLACK	
Odometer	168924 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	110/80R14	MAXXIS	3	
L/H Front Tyre				
R/H Rear Tyre	140/70R14	MAXXIS	3	
L/H Rear Tyre				
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	15/12/2024	Inspection Date	19/12/2024 (16:57)	
Survey held at	CARROS CENTRE 60 JLN LAM HUAT #03-05 SINGAPORE 737869 – REPAIRER: JC MOTOR CONSULTANCY			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.				
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.				
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S




PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S




PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 6231S

