



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SD 8160V

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT FORK TUBE ASSY	NOT NECESSARY	640.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	225.00	-
1	HANDLE-BAR	BENT	285.00	135.00
1	HANDLE-BAR END	CUT	136.00	45.00
1	SET HAND GRIP	NOT NECESSARY	98.00	-
1	FRONT SIGNAL	NOT NECESSARY	280.00	-
1	PILOT LIGHT	NOT NECESSARY	880.00	-
1	CLUTCH LEVER	CUT	115.00	40.00
1	FRONT COVER - MATT	CUT	200.00	200.00
1	SIDE MIRROR	CUT	128.00	60.00
1	SET FAIRING ASSY	CRACKED	780.00	450.00
1	FRONT FOOTREST BRACKET	NOT NECESSARY	255.00	-
2	FRONT FOOTREST	CUT	168.00	90.00
1	GEAR PEDAL	CUT	125.00	125.00
2	REAR FOOTREST	CUT	145.00	65.00
1	REAR FOOTREST BRACKET	CUT	250.00	125.00
1	SWING ARM	NOT NECESSARY	685.00	-
1	SWING ARM SHAFT	NOT NECESSARY	180.00	-
1	REAR RIM SHAFT	NOT NECESSARY	165.00	-
1	REAR RIM	NOT NECESSARY	650.00	-
1	REAR BRAKE DISC	NOT NECESSARY	225.00	-
1	REAR LAMP	CRACKED	455.00	250.00
1	REAR FENDER	SMASHED	225.00	225.00
1	REAR FENDER BRACKET	BENT	380.00	250.00
1	REAR SIGNAL LH	SMASHED	180.00	60.00
1	REAR NUMBER PLATE LAMP	SMASHED	145.00	70.00
1	REAR COVER (MATT)	CRACKED	168.00	120.00
1	EXHAUST ASSY	NOT NECESSARY	685.00	-
1	EXHAUST PROTECTOR	CUT	135.00	135.00
1	EXHAUST PIPE END COVER	CUT	105.00	105.00

Report Ref No. CS/FCI24120292/Avp3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-909.30	-255.00
			8,183.70	2,295.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	BENT	38.00	20.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	SET STICKER (SN)	NECESSARY	100.00	60.00
			344.00	80.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	30.00
	TO PROVIDE LABOUR.		420.00	250.00
	TO REPAIR BODY FRAME.		480.00	200.00
			980.00	480.00
GRAND TOTAL			9,507.70	2,855.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	-----------------

Report Ref No. CS/FCI24120292/Avp3e2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.