

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 7140S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BROKEN	895.00	895.00
1	FRONT BUMPER SIDE RETAINER LH	BROKEN	86.50	86.50
1	HEADLAMP LH	BROKEN	1,285.00	1,285.00
1	FRONT FENDER LH	DENTED	698.20	698.20
1	FRONT FENDER COWLING LH	TORN	251.00	180.00
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,025.00	-
1	SIDE MIRROR LH	TO REPAIR SEE LABOUR	701.20	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	845.00	-
1	FRONT KNUCKLE ARM BEARING	NOT NECESSARY	226.00	-
	LESS 20% DISCOUNT		-1,202.58	-628.94
			4,810.32	2,515.76
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
1	FRONT WHEEL RIM LH (SN)	NOT NECESSARY	800.00	-
			865.00	30.00
	<u>LABOUR</u>			
	CUT OFF REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND SIDE MIRROR LH.		500.00	400.00
	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.		800.00	600.00
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	CONDUCT FULL WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION.		80.00	30.00
			1,830.00	1,030.00
	GRAND TOTAL		7,505.32	3,575.76

Report Ref No. CS/AGI24120294/Evp3e2(N)



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI24120294/Evp3e2(N)



**Automotive Assessor** 



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser**