



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 5533K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	REPLACED	2,493.97	1,950.00
1	FRONT BUMPER LAMP LH	REPLACED	278.67	278.67
1	FRONT BUMPER LAMP GARNISH LH	REPLACED	105.11	105.11
1	FRONT BUMPER BRACKET LH	REPLACED	257.89	211.10
1	FRONT BUMPER END TRIM LH	REPLACED	67.40	67.40
1	HEADLAMP LH	REPLACED	727.54	727.54
1	HEADLAMP GARNISH LH	REPLACED	174.20	174.20
1	HEADLAMP STAY LH	REPLACED	959.26	803.13
	LESS 25% DISCOUNT		-1,266.01	-1,079.29
			3,798.03	3,237.86
	<u>LABOUR</u>			
	LABOUR TO REPAIR & REPLACE FRONT DAMAGED PARTS.		1,000.00	450.00
	SPRAY PAINT ON FRONT AFFECTED AREA.		1,000.00	450.00
	CHECK WIRING & REFOCUS HEADLAMP.		60.00	20.00
	TUFF KOTE.		100.00	20.00
			2,160.00	940.00
	GRAND TOTAL		5,958.03	4,177.86
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00

Report Ref No. CS/LAW24120295/Tnh3e2(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.