



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
PKWA LAW PRACTICE LLC 480 LORONG 6 TOA PAYOH #16-01 HDB HUB EAST WING SINGAPORE 310480			Ref: CS/LAW24120295/Tnh3e2 (N)R1 Date: 16/01/2025 Code: L177	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SLW 3328Y	Veh. Inspected	XE 5533K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CC.50257.24.ECICS	Excess (\$)	0.00
	Assign From	JOEANN PHUA	Assign Date	12/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi FV51	c.c	12882
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	FV51JJA00407	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	12 R22.5	INNING	8 mm
	L/H Front Tyre	12 R22.5	INNING	8 mm
	R/H Rear Tyre	12 R22.5 (D)	INNING	8/8 mm
	L/H Rear Tyre	12 R22.5 (D)	INNING	8/8 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	01/06/2023	Inspection Date	06/01/2025
	Survey held at	CARPORT AUTO SERVICE BLK 3 PIONEER ROAD NORTH #01-24 SINGAPORE 628457		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	