



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 3449A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	TO REPAIR SEE LABOUR	1,125.00	-
1	FRT BUMPER	BUCKLED	879.00	586.10
1	FRT BUMPER SIDE RETAINER LH	CRACKED	45.00	45.00
1	FRT BUMPER SIDE GARNISH LH	CUT	112.00	112.00
1	FRT BUMPER LOWER	SERVICEABLE	512.00	-
1	HEADLAMP LH	MTG CRACKED	5,012.00	2,591.00
1	FRONT GRILLE	SERVICEABLE	398.00	-
1	FRT HEADLAMP LOWER BRACKET LH	TO REPAIR SEE LABOUR	75.00	-
1	FRONT FENDER LH	BENT	698.00	698.00
1	FRONT FENDER EMBLEM LH	NECESSARY	52.00	52.00
1	FRONT FENDER COWLING LH	CRACKED	169.00	169.00
1	FRONT FENDER TOP GARNISH LH	SERVICEABLE	189.00	-
1	FRONT KNUCKLE ARM BEARING LH	NECESSARY	198.00	198.00
1	FRONT KNUCKLE ARM LH	BENT	512.00	512.00
1	FRONT LOWER ARM LH	DISTORTED	456.00	456.00
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,125.00	-
	LESS 25% DISCOUNT		-2,889.25	-1,354.78
			8,667.75	4,064.32
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	FRONT SPORT RIM (SN)	DENTED	600.00	600.00
1	FRONT WHEEL HUB CAP (SN)	SERVICEABLE	100.00	-
1	SET FRT FENDER INNERSHIELD CLIP LH (SN)	NECESSARY	50.00	50.00
			800.00	700.00
<b><u>LABOUR</u></b>				
	CHECK WIRING.		100.00	20.00
	REMOVE AND REFIT FRONT UNDERCARRIAGE.		300.00	140.00
	CONDUCT WHEEL ALIGNMENT.		120.00	60.00

Report Ref No. CS/FCI24120296/Kvp3e2(N)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REALIGN HEADLAMP.		120.00	20.00
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF BONNET, FRT HEADLAMP LOWER BRACKET LH AND FRONT DOOR LH.		600.00	400.00
	SPRAY PAINTING.		1,000.00	500.00
			2,240.00	1,140.00
<b>GRAND TOTAL</b>			<b>11,707.75</b>	<b>5,904.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,700.00</b>

Report Ref No. CS/FCI24120296/Kvp3e2(N)

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.