

ASS. REC. BY:

REF:

1002/CS/FCI24120296/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SHA 7008H

Policy No.

Claims No. D24011040MFCT

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/12/24 11:00 AM @ 4700h Carw (red 4735, 50%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S + RS. \$

: Fuel

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 93911482

Estimation

Date:

19/12/2024

Vehicle:

SMV3449A

Make / Model:

TOYOTA PRIUS

Not Worked
L1 Bay 84700/-
Repair After 05 days

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BONNET	1	\$ 1,125.00	\$ 1,125.00
2	FRT BUMPER	1	\$ 879.00	\$ 879.00
3	FRT BUMPER SIDE RETAINER LH	1	\$ 45.00	\$ 45.00
4	FRT BUMPER SIDE GARNISH LH	1	\$ 112.00	\$ 112.00
5	FRT BUMPER LOWER	1	\$ 512.00	\$ 512.00
6	HEADLAMP LH	1	\$ 2,591.00	\$ 5,012.00
7	FRONT GRILLE	1	\$ 398.00	\$ 398.00
8	FRT HEADLAMP LOWER BRACKET LH	1	\$ 75.00	\$ 75.00
9	FRONT FENDER LH	1	\$ 698.00	\$ 698.00
10	FRONT FENDER EMBLEM LH	1	\$ 52.00	\$ 52.00
11	FRONT FENDER COWLING LH	1	\$ 169.00	\$ 169.00
12	FRONT FENDER TOP GARNISH LH	1	\$ 189.00	\$ 189.00
13	FRONT KNUCKLE ARM BEARING LH	1	\$ 198.00	\$ 198.00
14	FRONT KNUCKLE ARM LH	1	\$ 512.00	\$ 512.00
15	FRONT LOWER ARM LH	1	\$ 456.00	\$ 456.00
16	FRONT DOOR LH	1	\$ 1,125.00	\$ 1,125.00
	TOTAL PART			\$ 10,432.00
	LIST DOWN	25%		\$ 2,608.00
	AFTER LIST DOWN			\$ 7,824.00
SPECIAL NETT				
1	FRT BUMPER CLIP SET	1	\$ 50.00	\$ 50.00
2	FRONT SPORT RIM	1	\$ 600.00	\$ 600.00
3	FRONT WHEEL HUB CAP	1	\$ 100.00	\$ 100.00
4	FRT FENDER INNERSHIELD CLIP SET LH	1	\$ 50.00	\$ 50.00
	TOTAL AMOUNT			\$ 800.00
LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	REMOVE AND REFIT FRONT UNDERCARRIAGE	1	\$ 300.00	\$ 300.00
3	CONDUCT WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
4	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00
5	PANEL BEAT	1	\$ 600.00	\$ 600.00
6	SPRAY PAINTING	1	\$ 1,000.00	\$ 1,000.00
	TOTAL AMOUNT			\$ 2,240.00
Parts Replacement Amount				\$ 7,595.00
Total Amount for Labour				\$ 1,840.00
Total Amount				\$ 9,435.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insured Company

Acknowledged by Repairer:

Signature:

Date:

201
140/-
601
201
400
500/-