

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURANCE BHD		R	ef:	CS3/LPC24120297/Kqh3e2(N)	
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			ate:	05/03/2025	
	ATTN: HUEY NI		C	ode:	LPC2	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBA 863Y	Veh. Inspected		GBM 475X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	24/24/25/VC05/030344	Excess (\$)		0.00	
	Assign From	HUEY NI	Assign Date		20/12/2024	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA VAN FUN STYLE TURBO	c.c		658	
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	JJ14105033	Colour		BLUE	
	Odometer	38860 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	165/65 R14	YOKOHAMA		8 mm	
	L/H Front Tyre	165/65 R14	YOKOHAMA		8 mm	
	R/H Rear Tyre	165/65 R14	YOKOHAMA		8 mm	
	L/H Rear Tyre	165/65 R14	YOKOHAMA		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
5.	General Information					
	Accident Date	16/12/2024	Inspect Date / Tir	me	20/12/2024 (04:18 PM)	
	Survey held at	TY AUTOCARE SERVICES				
		5033 ANG MO KIO INDUSTRIAL PARK 2 #01-271 SINGAPORE 569536				
5a.	a. Remarks					
	A) MARKET VALUE: \$66,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$22,086.00=NETT VALUE: \$43,914.00 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC24120297/Kqh3e2(N)

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

PEOP Auto Occupioni OAE License I Approxima

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$