

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24120301/EVP3E2**Date:** 23/01/2025REFERENCE

Insured/Claimant:	EE KEAN LING CHRISTOPHER	Policy No:	MPC24A00315601
Date of Loss:	18/12/2024	Nature of Claim:	OD
		Claim No:	DMPC2401748H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC629C	Engine No:	B4204T192587275
Make & Model:	VOLVO V40, 1.5 T2 (A)	Chassis No:	YV1MV41L0K2546702
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	94301 km
Colour:	Blue		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,200.30	3,718.00	6,482.30	63.55
Miscellaneous Items	380.00	304.00	76.00	20.00
Labour	1,610.00	785.00	825.00	51.24
Paintwork Labour	600.00	400.00	200.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,790.30	5,207.00	7,583.30	59.29
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	12,790.30	4,150.00	8,640.30	67.55
+ GST 9.00/9.00% (S\$)	1,151.13	373.50	777.63	67.55
Nett Amount (S\$)	13,941.43	4,523.50	9,417.93	67.55

INSPECTION

Date of Assignment:	20/12/2024	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	20/12/2024	Inspected At:	Progressive Car Care Pte Ltd (HQ)
			Blk 3022A Ubi Road 1, #01-45/46
			Singapore 408716
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2025)
Parts:	144	VOLVO V40 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC629C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER (WCP)	Deformed	1,350.00 F	*1,350.00 F
2	1	NA	*REAR BUMPER SIDE RETAINER - RH (WCP)	Not Necessary	80.00 F	*- F
3	10	NA	*REAR BUMPER CLIPS (WCP)	Necessary	60.00 F	*60.00 F
4	1	NA	*REAR BUMPER SIDE LOWER COVER - RH (WCP)	Repair	260.00 F	*- F
5	1	NA	*TAILLAMP - RH (WCP)	Cut	470.00 F	*470.00 F
6	1	NA	*REAR FENDER - RH (WCP)	Repair	1,580.00 F	*- F
7	1	NA	*REAR FENDER COWLING - RH (WCP)	Not Necessary	238.00 F	*- F
8	10	NA	*REAR FENDER COWLING CLIPS - RH (WCP)	Not Necessary	90.00 F	*- F
9	1	NA	*REAR RIM - RH (WCP)	Cut	1,500.00 F	*1,500.00 F
10	1	NA	*REAR KNUCKLE ARM - RH (WCP)	Not Necessary	950.00 F	*- F
11	1	NA	*REAR WHEEL BEARING - RH (WCP)	Not Necessary	620.00 F	*- F
12	1	NA	*REAR LOWER ARM - RH (WCP)	Not Necessary	950.00 F	*- F
13	1	NA	*REAR CONTROL ARM - RH (WCP)	Not Necessary	280.00 F	*- F
14	1	NA	*REAR SIDE ARM - RH (WCP)	Not Necessary	165.00 F	*- F
15	1	NA	*REAR ABSORBER - RH (WCP)	Not Necessary	380.00 F	*- F
16	1	NA	*REAR TOP ARM - RH (WCP)	Not Necessary	300.00 F	*- F
F=Franchise part.						
Sub Total (S\$)					9,273.00	3,380.00
+ Margin on L,N Items 10.00/10.00% (S\$)					927.30	338.00
Total Parts (S\$)					10,200.30	3,718.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR TYRE - RH (TORN) (80%)	380.00	304.00
Sub Total (\$)			380.00	304.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	600.00	400.00
Labour Items				
2	TO KNOCK OUT DENTS; CUT/WELD FENDER, REMOVE, REPLACE ACCIDENT PORTIONS	New	990.00	400.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REFIT GARNISH TO FACILITATE REPAIR	New	150.00	80.00
5	TO 4 WHEEL ALIGNMENT	New	75.00	75.00
6	TO REMOVE; REPLACE REAR RIM RH & TYRE BALANCING	New	45.00	30.00
7	TO REMOVE; REPLACE REAR RH UNDERCARRIAGE	New	300.00	150.00
8	ANTI RUST	New	30.00	30.00
Gross Labour Cost (\$)			2,210.00	1,185.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >