



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ASTER QUEK

Ref: CS/INC24120302/Avh3m4(N)

Date: 24/03/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 2246T	Veh. Inspected	SMP 450X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1309141-001	Excess (\$)	0.00
Assign From	ANNA YEO	Assign Date	20/12/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTEZB3GH70J004745	Colour	BLACK
Odometer	78131 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50R18	TRIANGLE	6 mm
L/H Front Tyre	235/50R18	TRIANGLE	6 mm
R/H Rear Tyre	235/50R18	TRIANGLE	6 mm
L/H Rear Tyre	235/50R18	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/12/2024	Inspect Date / Time	20/12/2024 (02:51 PM)
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**