

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 1982R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT COVER	BENT	2,350.00	1,712.80
1	REAR BUMPER	CRACKED	887.60	887.60
1	LEFT HAND REAR BUMPER RETAINER	SERVICEABLE	224.00	-
1	RIGHT HAND REAR BUMPER RETAINER	SERVICEABLE	224.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR BOOT INNER GARNISH	SERVICEABLE	580.00	-
1	REAR BOOT INNER FLOORING	TO REPAIR SEE LABOUR	625.00	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	425.00	-
1	REAR BOOT INNER HANDLE	SERVICEABLE	52.50	-
1	REAR KEYLESS SENSOR	SERVICEABLE	80.00	-
1	REAR BOOT COVER INNER GARNISH	SERVICEABLE	520.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	632.20	-
	LESS 25% DISCOUNT		-1,680.08	-680.10
			5,040.22	2,040.30
	SPECIAL NETT ITEMS			
1	REAR REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	LABOUR TO REPLACE BODY ITEMS. INCLUSIVE OF THE REPAIR OF REAR BOOT INNER FLOORING, REAR BOOT LOCK AND REAR END PANEL.		700.00	500.00
	LABOUR TO CONDUCT WIRING & ELECTRICAL FAULT TEST.		40.00	20.00
	LABOUR TO REMOVE REAR WINDSCREEN TO REPLACE REAR BOOT COVER.		120.00	120.00
	LABOUR TO ANTI-RUST END PANEL.	NOT NECESSARY	40.00	-
	LABOUR TO SPRAY PAINT REAR BOOT COVER (INSIDE- OUT) AND REAR BUMPER.		700.00	600.00
			1,600.00	1,240.00
	GRAND TOTAL		6,840.22	3,480.30

Report Ref No. CS/FCI24120304/Knp3m4(N)





RECOMMENDED COST OF LUMP SUM REPAIRS		2,750.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI24120304/Knp3m4(N)

KONG SENG CHEONG

Licensed Appraiser