

CS/SMO24070028/Anh3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To In: \_\_\_\_\_ Vehicle No: \_\_\_\_\_  
 at V/O: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHCIS63A Yr Regn: 2020, March  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai Tonig C.D. 1580  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 564863 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH C851CVL4189939  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 01/07/24  
 Survey held at Comfort Logany  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Sampo</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV : Yes C</u>
	<u>PV : No C</u>
	<u>Nett :</u>

We will be advising our Principal a cost of repair of LS \$1,750/- with 2 days of repair (red, \$929.59, 34%)

Date/Time, File Pass to?

1) \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$1 \_\_\_\_\_

Photos \_\_\_\_\_

## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 01.07.2024MODEL: Hyundai IoniqVEHICLE NO.: SHC1563A

SMF6888E

INSURANCE: SOMPO *45)*MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper ?	1		\$ 459.40
	Rear Bumper Centre Moulding <i>Rehind</i>	1		\$ 451.25
	Rear Bumper Lower Moulding <i>new</i>	1		\$ 155.00
	Rear Bumper Reinforcement ?	1		\$ 394.80
	Rear Bumper Rein-Brkt RH / LH ?	2	\$ 138.10	\$ 276.20
	Rear Bumper Clips <i>new</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Tow Cover <i>new</i>	1		\$ 98.80
	Rear Bumper FogLamp ?	1		\$ 201.50
	Rear Smart Key Antenna ?	1		\$ 40.50
SUB TOTAL				\$ 2,099.45
LESS 25%				\$ 524.86
DISCOUNTED TOTAL				<b>\$ 1,574.59</b>
	Rear No. Plate With Trim Cover <i>Chuld</i>	1		\$ 55.00
	Reverse Sensors ?	1		\$ 180.00
	Rear Bumper Mat <i>lit</i>	1		\$ 50.00
NETT TOTAL				<b>\$ 285.00</b>
SPARE PARTS TOTAL				<b>\$ 1,859.59</b>
<u>Labour Charge</u>				
Panel Beating				\$ 400.00
Spray Painting Charge				\$ 300.00
Remove/Refix Reverse Sensor				\$ 120.00
TOTAL LABOUR				<b>\$ 820.00</b>
ESTIMATE TOTAL				<b>\$ 2,679.59</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian King  
adrian.king@kicauto.com  
n/s 01/07/24  
03 Aug.



### Workshops

205 Braddell Road Singapore 579701  
59 Loyang Drive Singapore 508969  
383 Sin Ming Drive Singapore 575717  
45 Pandan Road Singapore 609286

Date/Time: 01.07.2024 11:29

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5945232

JC NO305596144

STOMER

/MS COMFORT TRANSPORTATION PTE LTD  
STOMER NO. 7010045  
DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

(R) (O)  
(P)

COUNT CARD NO.

REGN NO:

SHC1563A

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

30.06.2024 00:55

DATE/TIME IN

YR OF MANU.

11.03.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU189939

COMPLETION DATE/TIME:


### JOB DESCRIPTION

dent Date: 29.06.2024  
RE: 3P 29.06.2024

10

LABOR CODE  
PB

DESCRIPTION  
LUMPSUM REPAIR-SHC1563A-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: SHC1563A LIMITS

Vehicle No.: SHC1563A

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard