

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070029/UMA3Q2

Date: 06/09/2024

REFERENCE

|                       |                                       |                      |                 |
|-----------------------|---------------------------------------|----------------------|-----------------|
| Handling Insurer:     | India International Insurance Pte Ltd | Policy No:           | D24MPCM000773   |
| Claimant Vehicle No : | SML621R                               | Insured Vehicle No : | SNB8310B        |
| Date of Loss:         | 27/06/2024                            | Nature of Claim:     | TP              |
|                       |                                       | Claim No:            | MPC2024D0007661 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SML621R                      | Engine No:  | L13B14101163      |
| Make & Model:               | HONDA JAZZ, 1.3 CVT (A)      | Chassis No: | JHMGK3850KS214349 |
| Reg. Date:                  | 03/05/2019 (Man. Year: 2019) | Odometer:   | 48425 km          |
| Colour:                     | Red                          |             |                   |
| Engine Capacity:            | 1318 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 175/65 R15    | Rear Tyre Size:  | 175/65 R15    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------------|------------|------------|------------|--------|
| Parts                                    | 11,673.08  | 1,373.36   | 10,299.72  | 88.23  |
| Miscellaneous Items                      | 0.00       | 0.00       | 0.00       |        |
| Labour                                   | 4,270.00   | 1,130.00   | 3,140.00   | 73.54  |
| Paintwork Labour                         | 0.00       | 0.00       | 0.00       |        |
| Towing                                   | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)             | 15,943.08  | 2,503.36   | 13,439.72  | 84.30  |
| Approved Total (Overridden) (S\$)        |            | 2,000.00   |            |        |
| (S\$)                                    | 15,943.08  | 2,000.00   | 13,943.08  | 87.46  |
| + GST 9.00/9.00% (S\$)                   | 1,434.88   | 180.00     | 1,254.88   | 87.46  |
| Nett Amount (S\$)                        | 17,377.96  | 2,180.00   | 15,197.96  | 87.46  |
| + Car Rental (4.0 x S\$100.00/day) (S\$) |            | 400.00     |            |        |
| (S\$)                                    |            | 2,580.00   |            |        |
| Liabe Amount (50.00%) (S\$)              |            | 1,290.00   |            |        |
| + Doc/Search Fee (S\$)                   |            | 27.25      |            |        |
| Nett Liability (S\$)                     |            | 1,317.25   |            |        |
| Global Sum Settlement (S\$)              |            | 1,300.00   |            |        |

INSPECTION

|                             |            |               |                                   |
|-----------------------------|------------|---------------|-----------------------------------|
| Date of Assignment:         | 03/07/2024 |               |                                   |
| Date Inspected:             | 03/07/2024 | Inspected At: | SPEEDWERKZ PTE LTD (Autobay) (HQ) |
|                             |            |               | 1 KAKI BUKIT AVENUE 6 #01-73      |
|                             |            |               | Singapore 417883                  |
| Estimated Period of Repair: | 3.0 days   |               |                                   |

---

**Adjuster:**    MARCUS CHUA

**Manager:**    Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                          |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                          |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 29 Jul 2024)            |
| Parts:        | 144                                                                                                                                                                          | HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                        |
| Print Code:   | (Unsubmitted, no print-code for SML621R)                                                                                                                                     |                                                          |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                          |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                          |

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT BONNET LOCK CABLE         | Not Necessary | 65.00 FL    | *- FL      |
| 2   | 1   |          | *FRONT BONNET INSULATOR          | Not Necessary | 175.20 FL   | *- FL      |
| 3   | 2   |          | *FRONT BONNET HINGE              | Not Necessary | 116.40 FL   | *- FL      |
| 4   | 1   |          | *FRONT BONNET LOCK               | Not Necessary | 88.60 FL    | *- FL      |
| 5   | 1   |          | *FRONT BONNET SEAL               | Not Necessary | 58.20 FL    | *- FL      |
| 6   | 1   |          | *FRONT BONNET                    | Not Necessary | 1,212.00 FL | *- FL      |
| 7   | 1   |          | *FRONT BUMPER                    | Cut / Torn    | 1,355.20 FL | *551.00 FL |
| 8   | 1   |          | *FRONT BUMPER TOW COVER          | Not Necessary | 48.60 FL    | *- FL      |
| 9   | 1   |          | *FRONT BUMPER LOWER GRILLE CTR   | Not Necessary | 189.90 FL   | *- FL      |
| 10  | 1   |          | *FRONT BUMPER FOG LAMP COVER RH  | Not Necessary | 172.50 FL   | *- FL      |
| 11  | 1   |          | *FRONT BUMPER REINFORCEMENT      | Not Necessary | 691.50 FL   | *- FL      |
| 12  | 1   |          | *SET FRONT BUMPER CLIPS          | Necessary     | 36.00 FS    | *30.00 FS  |
| 13  | 1   |          | *FRONT GRILLE ASSY               | Not Necessary | 431.80 FL   | *- FL      |
| 14  | 1   |          | *FRONT GRILLE CHROME MOULDING    | Not Necessary | 243.60 FL   | *- FL      |
| 15  | 1   |          | *FRONT GRILLE LOGO               | Not Necessary | 89.80 FL    | *- FL      |
| 16  | 1   |          | *FRONT GRILLE TOP GARNISH        | Not Necessary | 120.30 FL   | *- FL      |
| 17  | 10  |          | *FRONT GRILLE TOP GARNISH CLIPS  | Not Necessary | 45.00 FL    | *- FL      |
| 18  | 2   |          | *FRONT GRILLE SIDE BRACKET       | Not Necessary | 76.40 FL    | *- FL      |
| 19  | 1   |          | *FRONT HEADLAMP LH               | Cracked       | 1,967.00 FL | *980.00 FL |
| 20  | 2   |          | *FRONT HEADLAMP SIDE GARNISH     | No such part  | 96.40 FL    | *- FL      |
| 21  | 1   |          | *FRONT HEADLAMP LOWER BRACKET    | Not Necessary | 179.00 FL   | *- FL      |
| 22  | 1   |          | *FRONT SUPPORT PANEL             | Repair        | 758.00 FL   | *- FL      |
| 23  | 1   |          | *FRONT FENDER LH                 | Repair        | 878.50 FL   | *- FL      |
| 24  | 1   |          | *FRONT FENDER INNER SHIELD       | Torn          | 221.60 FL   | *148.20 FL |
| 25  | 1   |          | *FRONT FENDER SUPPORT BEAM       | Not Necessary | 347.50 FL   | *- FL      |
| 26  | 1   |          | *FRONT FENDER INNER SUPPORT BEAM | Not Necessary | 225.60 FL   | *- FL      |
| 27  | 1   |          | *FRONT KNUCKLE ARM LH            | Not Necessary | 625.00 FL   | *- FL      |
| 28  | 1   |          | *FRONT WHEEL BEARING LH          | Not Necessary | 336.00 FL   | *- FL      |
| 29  | 1   |          | *FRONT WHEEL BEARING HUB LH      | Not Necessary | 264.00 FL   | *- FL      |
| 30  | 1   |          | *FRONT LOWER ARM                 | Not Necessary | 390.00 FL   | *- FL      |
| 31  | 1   |          | *FRONT STABILIZER BAR LINK LH    | Not Necessary | 148.00 FL   | *- FL      |
| 32  | 1   |          | *FRONT TIE ROD LH                | Not Necessary | 196.00 FL   | *- FL      |
| 33  | 2   |          | *FRONT TIE ROD END LH            | Not Necessary | 190.00 FL   | *- FL      |
| 34  | 1   |          | *FRONT BUMPER CLIP               | Repeated      | 50.00 FS    | *- FS      |
| 35  | 1   |          | *FRONT BONNET INSULATOR CLIP     | Not Necessary | 40.00 FS    | *- FS      |
| 36  | 1   |          | *FRONT NUMBER PLATE              | Not Necessary | 45.00 FS    | *- FS      |
| 37  | 1   |          | *SPORT RIM                       | Repair        | 1,500.00 FS | *- FS      |
| 38  | 4   |          | *TYRE                            | Not Necessary | 400.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                    |           |          |
|----------------------------------------------------|-----------|----------|
| Sub Total (S\$)                                    | 14,073.60 | 1,709.20 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 2,400.52  | 335.84   |
| Total Parts (S\$)                                  | 11,673.08 | 1,373.36 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                  |          |                 |                 |
| 1                               | CHECK WIRING & DIAGNOSTIC FAULT CODE                                             | New      | 120.00          | 0.00            |
| 2                               | REMOVE REFIX AND RENEW FRONT UNDER CARRIAGE & SUSPENSION                         | New      | 400.00          | 0.00            |
| 3                               | CHECK WHEEL ALIGNMENT                                                            | New      | 150.00          | 50.00           |
| 4                               | LABOUR CHARGE FOR KNOCK DENT ON FRONT DAMAGE PORTION ,CUT ,WELDING & RENEW PARTS | New      | 2,000.00        | 480.00          |
| 5                               | TO SPRAY PAINTING AND ETC                                                        | New      | 1,600.00        | 600.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                  |          | <b>4,270.00</b> | <b>1,130.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >