

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120**Our File No:** CS/AIG24120322/AVP3E2**Date:** 27/02/2025REFERENCE

Insured/Claimant:	WONG MUI KWAI	Policy No:	1800096556	
Date of Loss:	20/12/2024	Nature of Claim:	OD	Claim No: 2811711896SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7269X		
Make & Model:	AUDI A4, 1.4 (A)	Engine No:	CVK064494
Reg. Date:	31/08/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF42JN015337
Colour:	Black	Odometer:	64271 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,888.00	3,247.92	2,640.08	44.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,292.00	2,172.00	2,120.00	49.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,180.00	5,419.92	4,760.08	46.76
- Excess (\$\$)	1,100.00	1,100.00	0.00	0.00
(\$\$)	9,080.00	4,319.92	4,760.08	52.42
+ GST 9.00/9.00% (\$\$)	817.20	388.79	428.41	52.42
Nett Amount (\$\$)	9,897.20	4,708.71	5,188.49	52.42

INSPECTION

Date of Assignment:	27/12/2024	
Date Inspected:	27/12/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	3,647.00 FS	*2,917.60 FS
2	1		*FRONT DOOR OUTER SEAL	Necessary	275.00 FS	*220.00 FS
3	1		*BANDING AGENT	Not Necessary	54.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	92.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	10.00 FS	*- FS
6	1		*FRONT DOOR CATCH - LH	Necessary	131.00 FS	*104.40 FS
7	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,179.00 FS	*- FS
8	1		*SUNDRIES	Necessary	500.00 FS	*5.92 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

5,888.00

3,247.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	350.00	280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,750.00	500.00
3	TO RESPRAY LHS FRONT DOOR AND LHS SILL APNEL	New	1,900.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			4,292.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >