



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 310C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR RH	DENTED/BENT	1,718.00	1,109.00
1	REAR DOOR TRIM RH	NOT NECESSARY	447.00	-
2	REAR DOOR HINGE RH	NOT NECESSARY	214.00	-
1	REAR DOOR CHROME MOULDING RH	NOT NECESSARY	175.00	-
1	REAR DOOR LOCK RH	NOT NECESSARY	397.00	-
1	REAR DOOR HANDLE RH	NOT NECESSARY	244.00	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	175.00	-
1	REAR DOOR GLASS RH	NOT NECESSARY	457.80	-
1	REAR DOOR GLASS MOULDING RH	NOT NECESSARY	175.60	-
1	ROCKER PANEL	NOT NECESSARY	1,257.00	-
1	REAR FENDER RH	BADLY DENTED	2,527.00	1,220.00
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	455.00	-
1	REAR BUMPER	CUT/TORN	1,356.00	936.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	145.00	-
1	REAR BUMPER REFLECTOR COVER RH	NOT NECESSARY	145.00	-
1	TAILLAMP RH	NOT NECESSARY	834.00	-
1	TAILLAMP PANEL RH	NOT NECESSARY	204.60	-
	LESS 20% DISCOUNT		-2,185.40	-653.00
			8,741.60	2,612.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR RIM RH (SN)	CUT/WARPED	700.00	380.00
1	REAR DOOR CLIP (SN)	NOT NECESSARY	55.00	-
1	SET REAR FENDER GLASS SEALANT (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
			855.00	440.00
<u>LABOUR</u>				
	CHECK WIRING AND LIGHTING SYSTEM.		150.00	20.00
	REMOVE AND REFIT DOOR MECHANISM.		600.00	50.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		150.00	60.00

Report Ref No. CS/FCI24120326/Uvp3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS.		1,600.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	700.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	50.00
			4,200.00	1,480.00
GRAND TOTAL			13,796.60	4,532.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS/FCI24120326/Uvp3m4(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.