



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: JOANNE YONG		Ref: CS/FCI24120326/Uvp3m4(N) Date: 06/01/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SH 7064C	Veh. Inspected	SFY 310C
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24011148MFCT	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	20/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71216142	Colour	PURPLE
Odometer	56508 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/50R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/50R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/50R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/50R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/12/2024	Inspection Date	24/12/2024
Survey held at	CARSMITH PTE LTD 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	