



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 9458Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT SIDE PANEL - LH	DENTED	\$285.00	\$285.00
1	FRONT SIDE PANEL MIRROR - LH	CUT	\$255.00	\$255.00
1	FRONT HEAD LAMP - LH	NOT NECESSARY	\$355.00	\$0.00
1	FRONT HEAD LAMP BRACKET - LH	NOT NECESSARY	\$115.00	\$0.00
1	FRONT SIDE LAMP - LH	NOT NECESSARY	\$178.20	\$0.00
1	FRONT BUMPER	NOT NECESSARY	\$725.20	\$0.00
2	FRONT BUMPER SIDE BRACKET @\$78.20	NOT NECESSARY	\$156.40	\$0.00
1	FRONT BUMPER BRACKET - LH	NOT NECESSARY	\$188.00	\$0.00
1	FRONT BUMPER AIR-DUCT	NOT NECESSARY	\$187.30	\$0.00
1	FRONT L/H DOOR	DENTED	\$1,050.00	\$1,050.00
1	FRONT L/H DOOR INNER LOCK	NOT NECESSARY	\$265.80	\$0.00
1	FRONT L/H SIDE MIRROR	CUT	\$380.00	\$380.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$492.50)
			\$4,140.90	\$1,477.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT L/H DOOR BODY LOGO (SN)	NECESSARY	\$350.00	\$250.00
			\$350.00	\$250.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM	NOT NECESSARY	\$60.00	\$30.00
	TUFF KOTE		\$100.00	\$0.00
	PANEL BEATING		\$400.00	\$300.00
	SPRAY PAINTING		\$400.00	\$300.00
			\$960.00	\$630.00

GRAND TOTAL		\$5,450.90	\$2,357.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,800.00
Report Ref No: CS/LIP24060034/Avp3			

MARKET VALUE: \$115,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$18,143.00=NETT VALUE: \$96,857.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING