

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120328/AVP3E2**Date:** 04/09/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003057146		
Claimant Vehicle No :	SKB519E	Insured Vehicle No :	SLQ5917R		
Date of Loss:	19/12/2024	Nature of Claim:	TP	Claim No:	385886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB519E	Engine No:	27186030054641
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2074472F043814
Reg. Date:	24/08/2010 (Man. Year: 2010)	Odometer:	148743 km
Colour:	Red		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	80,556.05	42,048.36	38,507.69	47.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,270.00	5,830.00	7,440.00	56.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	93,826.05	47,878.36	45,947.69	48.97
Approved Total (Overridden) (S\$)		38,300.00		
Nett Amount (S\$)	93,826.05	38,300.00	55,526.05	59.18

INSPECTION

Date of Assignment:	23/12/2024		
Date Inspected:	23/12/2024	Inspected At:	Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	22.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2025)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB519E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,231.00 FL	*1,895.00 FL
2	1		*FRONT BUMPER SENSOR (6PCS)	Damaged (2Pcs Only)	2,310.00 FL	*580.00 FL
3	1		*FRONT BUMPER SENSOR HOLDER (6PCS)	Necessary	408.00 FL	*150.00 FL
4	2		*FRONT BUMPER FOG LAMP (LED)	Cracked	1,175.20 FL	*820.00 FL
5	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	337.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	385.90 FL	*248.00 FL
7	1		*FRONT BUMPER BOTTOM GARNISH	Not Necessary	682.00 FL	*- FL
8	2		*FRONT BUMPER CORNER BRACKET	Not Necessary	42.00 FL	*- FL
9	2		*FRONT BUMPER CENTER LOWER BRACKET	Not Necessary	252.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	850.00 FL	*850.00 FL
11	1		*FRONT BUMPER SPONGE (3PCS)	Cracked	888.00 FL	*160.00 FL
12	2		*FRONT HEADLAMP	Cracked	5,971.20 FL	*5,971.20 FL
13	1		*FRONT HEADLAMP NOZZLE	N/S Cracked	572.00 FL	*286.00 FL
14	2		*FRONT HEADLAMP NOZZLE COVER	Not Necessary	196.00 FL	*- FL
15	2		*FRONT FENDER INNER COWLING	Not Necessary	496.00 FL	*- FL
16	1		*FRONT GRILLE LOGO	Necessary	158.90 FL	*158.90 FL
17	1		*FRONT GRILLE CENTER SUPPORT BRACKET	Smashed	105.60 FL	*105.60 FL
18	1		*FRONT GRILLE CENTER	Cracked	1,472.50 FL	*1,472.50 FL
19	2		*FRONT FENDER	Buckled	2,851.20 FL	*1,978.00 FL
20	1		*BONNET	Dented	2,946.00 FL	*2,690.00 FL
21	1		*BONNET BOTTOM LOCK	Jammed	198.00 FL	*198.00 FL
22	1		*BONNET INSULATOR	Not Necessary	316.00 FL	*- FL
23	2		*BONNET STOPPER	Not Necessary	38.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Distorted	1,986.70 FL	*620.00 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	188.00 FL	*188.00 FL
26	1		*FRONT RADIATOR TOP PANEL	Not Necessary	188.00 FL	*- FL
27	1		*FRONT RADIATOR	Distorted	1,897.60 FL	*1,490.00 FL
28	1		*FRONT CONDENSER	Distorted	1,624.50 FL	*1,295.00 FL
29	2		*FRONT CONDENSER AIR GUIDES	Torn	179.20 FL	*179.20 FL
30	1		*FRONT CONDENSER FAN ASSY	Cracked	1,758.90 FL	*1,200.00 FL
31	1		*FRONT TURBO COOLER	Dented	2,108.60 FL	*1,250.00 FL
32	1		*AIR GUARD	Not Necessary	178.00 FL	*- FL
33	2		*HEAD REST	Not Necessary	1,371.80 FL	*- FL
34	1		*BOOTLID	Distorted	2,846.80 FL	*2,695.00 FL
35	1		*BOOTLID THIRD BRAKE LAMP	Not Necessary	498.50 FL	*- FL
36	1		*BOOTLID LOGO	Necessary	98.60 FL	*98.60 FL
37	1		*BOOTLID OUTER CHROME	Not Necessary	398.50 FL	*- FL
38	2		*BOOTLID STOPPER	Not Necessary	90.00 FL	*- FL
39	2		*BOOTLID HINGE	Not Necessary	350.00 FL	*- FL
40	2		*BOOTLID LAMP	Not Necessary	1,379.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*BOOTLID BREAKDOWN SIGN BOARD	Not Necessary	256.00 FL	*- FL
42	1		*BOOTLID TOP LOCK	Damaged	398.40 FL	*398.40 FL
43	1		*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
44	1		*BOOTLID AUTO LOCK MOTOR	Not Necessary	796.00 FL	*- FL
45	1		*BOOTLID AUTO CLOSING SYSTEM	Not Necessary	1,965.00 FL	*- FL
46	1		*BOOTLID WEATHER STRIP	Not Necessary	245.00 FL	*- FL
47	1		*REAR BUMPER	Deformed	1,933.00 FL	*1,745.00 FL
48	1		*REAR BUMPER LOWER	Distorted	936.30 FL	*425.00 FL
49	1		*REAR BUMPER TOWING COVER	Distorted	84.00 FL	*84.00 FL
50	2		*REAR BUMPER SIDE RETAINER	Not Necessary	197.20 FL	*- FL
51	2		*REAR BUMPER BRACKET	Bent	130.00 FL	*130.00 FL
52	1		*REAR BUMPER BOTTOM SIDE GARNISH RH	Deformed	210.00 FL	*210.00 FL
53	2		*REAR BUMPER SIDE BRACKET	Not Necessary	84.00 FL	*- FL
54	1		*REAR BUMPER CENTRE FRAME	Cracked	342.00 FL	*342.00 FL
55	1		*REAR BUMPER REINFORCEMENT	Dented	894.00 FL	*894.00 FL
56	2		*TAILLAMP	Cracked	1,751.60 FL	*1,751.60 FL
57	2		*REAR FENDER	Not Necessary	4,289.20 FL	*- FL
58	2		*REAR FENDER TOP GARNISH	Not Necessary	196.00 FL	*- FL
59	1		*REAR FENDER COWLING	N/S Torn	396.00 FL	*198.00 FL
60	2		*REAR FENDER INNER TRIM	Not Necessary	1,294.00 FL	*- FL
61	1		*REAR END PANEL	Distorted	1,591.00 FL	*1,195.00 FL
62	1		*REAR END INNER PANEL	Not Necessary	364.00 FL	*- FL
63	1		*REAR END PANEL INNER GARNISH	Deformed	285.00 FL	*285.00 FL
64	1		*REAR FLOOR PANEL	Distorted	2,887.00 FL	*1,650.00 FL
65	1		*REAR FLOOR PANEL CENTER BOARD	Not Necessary	554.00 FL	*- FL
66	1		*REAR FLOOR SIDE PANEL	Repair	1,467.80 FL	*- FL
67	1		*REAR SPARE TYRE LOCK BOLT	Cracked	61.00 FL	*61.00 FL
68	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	1,564.00 FL	*580.00 FL
69	4		*REVERSE SENSOR HOLDER	Necessary	256.00 FL	*100.00 FL
70	1		*REVERSE SENSOR WIREHARNES	Not Necessary	967.00 FL	*- FL
71	1		*REAR EXHAUST BOX WITH CHROME PIPE	Bent	2,660.00 FL	*1,825.00 FL
72	2		*REAR EXHAUST INSULATOR	Crumpled	392.00 FL	*392.00 FL
73	1		*REAR EXHAUST MOUNTING (4PCS)	Torn (1Pc Only)	388.00 FL	*45.00 FL
74	1		*FRONT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
75	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
76	1		*SET FRONT BUMPER BOTTOM GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
77	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
78	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
79	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
80	1		*FRONT FENDER SEALANT LH	Not Necessary	80.00 FS	*- FS
81	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
82	1		*REAR NUMBER PLATE	Missing	50.00 FS	*50.00 FS
83	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
84	1		*SET REAR BUMPER BOTTOM SIDE GARNISH CLIP RH	Not Necessary	50.00 FS	*20.00 FS
85	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
86	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
87	1		*SET BOOTLID MOULDING CLIP	Not Necessary	50.00 FS	*- FS
88	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
89	1		*SET REAR FENDER TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
90	1		*SET REAR FENDER COWLING CLIP	Necessary	50.00 FS	*25.00 FS
91	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
92	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
93	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
94	1		*REAR END INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
95	1		*SET REAR END PANEL INNER GARNISH CLIP	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	180.00 FS	*- FS
97	1		*REAR WHEEL WELL PANEL SEALANT	Necessary	250.00 FS	*60.00 FS
98	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
99	1		*FRONT DRIVER SEAT BELT	Activated	980.00 FL	*850.00 FL
100	1		*FRONT PASSENGER SEAT BELT	Activated	980.00 FL	*850.00 FL
101	1		*REAR PASSENGER SEAT BELT RH	Activated	980.00 FL	*850.00 FL
102	1		*REAR PASSENGER SEAT BELT LH	Activated	980.00 FL	*850.00 FL
103	1		*FRONT DRIVER HEAD REST	Not Necessary	850.00 FL	*- FL
104	1		*FRONT PASSENGER HEAD RESR	Not Necessary	850.00 FL	*- FL
105	1		*REAR PASSENGER HEAD REST RH	Not Necessary	850.00 FL	*- FL
106	1		*REAR PASSENGER HEAD REST LH	Not Necessary	850.00 FL	*- FL
107	1		*REAR PASSENGER SEAT AIRBAG BULLET RH	Activated	1,250.00 FL	*390.00 FL
108	1		*REAR PASSENGER SEAT AIRBAG BULLET LH	Activated	1,250.00 FL	*390.00 FL
109	1		*AIRBAG ECU	Activated	1,455.60 FL	*950.00 FL
110	1		*CONVERTIBLE TOP SENSOR RH	Activated	760.00 FL	*760.00 FL
111	1		*CONVERTIBLE TOP SENSOR LH	Activated	760.00 FL	*760.00 FL
112	1		*WIPER COVER LH	Not Necessary	165.20 FL	*- FL
113	1		*GAS SPRING FRONT BONNET RH	Not Necessary	178.00 FL	*- FL
114	1		*GAS SPRING FRONT BONNET LH	Not Necessary	178.00 FL	*- FL
115	1		*HOSE TOP SPARE TANK TO RAD	Not Necessary	145.20 FL	*- FL
116	1		*TOP HOSE	Not Necessary	198.20 FL	*- FL
117	1		*BOTTOM HOSE	Not Necessary	198.90 FL	*- FL
118	1		*BYPAS PIPE	Not Necessary	98.50 FL	*- FL
119	1		*INTERCOOLER COOLER LINING	Not Necessary	388.60 FL	*- FL
120	1		*INTERCOOLER PIPING LH	Bent	365.20 FL	*365.20 FL
121	1		*INTERCOOLER PIPING RH	Bent	365.20 FL	*365.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	89,254.50	46,675.40
- List Item Discount on L Items 10.00/10.00% (\$)	8,698.45	4,627.04
Total Parts (\$)	80,556.05	42,048.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS (FRONT)	New	2,000.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,600.00	800.00
3	REFOCUS HEADLAMP BEAM (FRONT)	New	80.00	30.00
4	RESET AIR BAG LIGHT (FRONT)	New	350.00	300.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC (FRONT)	New	380.00	150.00
6	PANEL BEATING, REMOVAL AND REPLACING PARTS (REAR)	New	2,000.00	1,200.00
7	TO SPRAY PAINT AFFECTED AREA (REAR)	New	2,000.00	800.00
8	TUFF COAT (REAR)	New	200.00	100.00
9	WIRING CHECK (REAR)	New	1,150.00	30.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY TO FACILITATE REPAIR (REAR)	New	200.00	80.00
11	TRANSFER BOOTLID MECHANISM (REAR)	New	120.00	60.00
12	CONDUCT WATER LEAKAGE TEST (REAR)	New	100.00	0.00
13	REMOVE AND REFIX REAR EXHAUST PIPE (REAR)	New	300.00	100.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	120.00	50.00
15	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)	New	120.00	50.00
16	RESET BOOTLID SYSTEM (REAR)	New	350.00	0.00
17	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
18	TO RESET AIRBAG SYSTEM	New	450.00	300.00
19	TO RESET CONVERTIBLE SOFT TOP, REALIGH AND PROGRAMMING	New	850.00	580.00
20	RESET HEAD REST AND CODING (FRONT)	New	650.00	0.00
Gross Labour Cost (S\$)			13,270.00	5,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >