

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAI	NCE BHD	R	ef:	CS3/LPC24120329/Kqh3e2(N)	
	300 BEACH ROAD SINGAPORE 1995) #17-04/07 THE CONCOURSE 55	D	ate:	02/01/2025	
	ATTN: GERALD PO	OH	C	ode:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBK 7087Y	Veh. Inspected		GBE 6347K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	24/24/25/VC05/030351	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		23/12/2024	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 (M)	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	VSKYBAM20Z0122986	Colour		MULTI COLOUR	
	Odometer	180471 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	GITI		9 mm	
	L/H Front Tyre	175/70 R14	GITI		9 mm	
	R/H Rear Tyre	175/70 R14	GITI		9 mm	
	L/H Rear Tyre	175/70 R14	GITI		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION.			-		
	DAMAGES SEE D	ETAILS.				
5.	General Information					
	Accident Date	19/12/2024	Inspect Date / Tir	me	23/12/2024 (10:30 AM)	
	Survey held at	KING'S AUTO AIR-CONDITIONING SERVICE				
		BLK 176 SIN MING DRIVE #02-10 SIN MING AUTOCARE SINGAPORE 575721				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC24120329/Kqh3e2(N)

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

DEOD Anta Organization OAE Linear LAnguarian

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$