

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120336/KNP3E2
Date: 08/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003599698
Claimant Vehicle No :	SNM4751E	Insured Vehicle No :	YP5762X
Date of Loss:	19/12/2024	Nature of Claim:	TP
		Claim No:	386345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNM4751E	Engine No:	2ZRZ052719
Make & Model:	TOYOTA COROLLA ALTIS, 1.8 HYBRID (A)	Chassis No:	MR2BZ3BE400012640
Reg. Date:	26/09/2023 (Man. Year: 2023)	Odometer:	91710 km
Colour:	Metallic Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,286.00	4,382.75	3,903.25	47.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,180.00	1,130.00	48.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,596.00	5,562.75	5,033.25	47.50
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	10,596.00	4,450.00	6,146.00	58.00
+ GST 9.00/9.00% (S\$)	953.64	400.50	553.14	58.00
Nett Amount (S\$)	11,549.64	4,850.50	6,699.14	58.00

INSPECTION

Date of Assignment:	23/12/2024	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat #05-21 Carros Centre Singapore 737869
Date Inspected:	23/12/2024 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
Parts: 143	TOYOTA COROLLA ALTIS 1.8 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNM4751E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,125.00 FL	*- FL
2	1		*FRONT BUMPER	Buckled / Mtg Cracked	821.00 FL	*533.00 FL
3	1		*FRONT BUMPER LOWER	Serviceable	582.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	98.00 FL	*98.00 FL
5	1		*FRONT BUMPER SIDE GARNISH LH	Serviceable	212.00 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP COVER LH	Serviceable	198.00 FL	*- FL
7	1		*SIDE MIRROR LH	Repair	698.00 FL	*- FL
8	1		*FRONT FENDRE LH	Bent	798.00 FL	*698.00 FL
9	1		*FRONT FENDER INNER SHIELD LH	Cracked	198.00 FL	*198.00 FL
10	1		*FRONT FENDER EMBLEM HYBRID LH	Necessary	52.00 FL	*52.00 FL
11	1		*FRONT GRILLE C/W CHROME	Serviceable	512.00 FL	*- FL
12	1		*HEADLAMP LH	Mtg Cracked	3,598.00 FL	*2,598.00 FL
13	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*50.00 FS
14	8		*FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	52.00 FS	*- FS
15	1		*FRONT TYRE LH	Serviceable	300.00 FS	*- FS
16	1		*FRONT SPORTS RIM	Dented	1,200.00 FS	*1,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,509.00	5,427.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,223.00	1,044.25
Total Parts (\$)	8,286.00	4,382.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	800.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	600.00
3	CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	WIRING CHECK }	New	200.00	20.00
5	REFOCUS HEADLAMP BEAM }	New	60.00	0.00
6	RESET ENGINE TROUBLE CODE	New	300.00	0.00
Gross Labour Cost (\$)			2,310.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >