

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AUTOMOTIVE EN	GRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24120337/Avp3m4(N)	
	FORCE) POLICE L	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675	Date	25/03/2025	
	ATTN: CUI FEN		Code	: SPF	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	QX 1495X	Veh. Inspected	SLR 6939R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	ACS/105/009/2024/065 (CF)	Excess (\$)	0.00	
	Assign From	LAI PENGCHONG	Assign Date	23/12/2024	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA AXIO HYBRID	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	NKE1657153249	Colour	BLACK	
	Odometer	85163 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/65R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/65R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/65R15	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/12/2024	Inspection Date	23/12/2024	
	Survey held at	JL PERFECT AUTOWORK PTE LTD			
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			