

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.12.2024

TO : **SPF** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLR6939R**
MODEL : **TOYOTA COROLLA AXIO**
DATE OF ACCIDENT : 19.12.2024
TIME OF ACCIDENT : 10:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 947.50	\$ 947.50
2	BOOT LID INSULATOR <i>new</i>	1	\$ 205.00	\$ 205.00
3	BOOT LID HINGE <i>new</i>	2	\$ 75.00	\$ 150.00
4	BOOT LID LOCK <i>Damaged</i>	1	\$ 105.00	\$ 105.00
5	BOOT LID LOWER CATCH <i>new</i>	1	\$ 42.00	\$ 42.00
6	BOOT LID LOGO <i>2</i>	1	\$ 58.00	\$ 58.00
7	BOOT LID EMBLEM 'AXIO' <i>new</i>	1	\$ 58.00	\$ 58.00
8	BOOT LD EMBLEM 'COROLLA'	1	\$ 50.00	\$ 50.00
9	BOOT LD EMBLEM 'HYBRID'	1	\$ 55.00	\$ 55.00
10	BOOT LID WEATHER STRIP <i>new</i>	1	\$ 189.70	\$ 189.70
11	BOOTLID OUTER MOULDING <i>new</i>	1	\$ 394.60	\$ 394.60
12	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 75.10	\$ 150.20
13	REAR BUMPER <i>Dented</i>	1	\$ 1,249.60	\$ 1,249.60
14	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 74.60	\$ 149.20
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 105.40	\$ 210.80
16	REAR BUMPER BRACKET <i>new</i>	2	\$ 85.20	\$ 170.40
17	TAIL LAMP <i>new combined</i>	2	\$ 579.40	\$ 1,158.80
18	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 98.00	\$ 196.00
19	TAIL LAMP PANEL <i>new</i>	2	\$ 245.80	\$ 491.60

TO : **SPF** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLR6939R**
 MODEL : **TOYOTA COROLLA AXIO**
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 10:50 HOURS

20	REAR FENDER INNER COWLING <i>new</i>	2	\$ 147.60	\$ 295.20	+
21	REAR FENDER INNER TRIM <i>new</i>	2	\$ 395.80	\$ 791.60	+
22	REAR END PANEL <i>Dented</i>	1	\$ 697.20	\$ 697.20	✓
23	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 229.40	\$ 229.40	✓
24	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 560.00	\$ 560.00	→ 380
25	REAR EXHAUST PIPE	1	\$ 940.00	\$ 940.00	+
26	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 245.70	\$ 245.70	+
27	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 58.00	\$ 232.00	+
28	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+

TOTAL PRICE \$ 10,082.50
 LESS 25% \$ 2,520.63
SUB TOTAL PRICE \$ 7,561.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS <i>new</i>	1	\$ 60.00	\$ 60.00	→ 30
3	BOOTLID OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
4	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
6	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
7	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 180.00	\$ 180.00	60
11	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	+
12	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	20

TOTAL \$ 1,460.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700

TO : **SPF** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLR6939R**
 MODEL : **TOYOTA COROLLA AXIO**
 DATE OF ACCIDENT : 19.12.2024
 TIME OF ACCIDENT : 10:50 HOURS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,090.00

TOTAL PARTS COST : \$ 9,021.88
 TOTAL LABOUR COST : \$ 5,090.00
 TOTAL REPAIR COST : \$ 14,111.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

LKK Auto hence notify the Repairer the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Replacement parts must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Admin
 2/5 23/12/24.
 06 Days