

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24120344/KVP3E2
Date: 16/01/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002259761
Claimant Vehicle No :	SKR3749D	Insured Vehicle No :	SLG4517X
Date of Loss:	26/11/2024	Nature of Claim:	TP
		Claim No:	382412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR3749D	Engine No:	1ZR485817
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104525895
Reg. Date:	03/02/2015 (Man. Year: 2015)	Odometer:	364736 km
Colour:	Metallic Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 3 mm	Rear Left Side:	Nexen 2 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Nexen 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,955.94	11,244.70	10,711.24	48.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,635.00	2,260.00	2,375.00	51.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,590.94	13,504.70	13,086.24	49.21
Approved Total (Overridden) (S\$)		10,800.00		
Nett Amount (S\$)	26,590.94	10,800.00	15,790.94	59.38

INSPECTION

Date of Assignment:	23/12/2024		
Date Inspected:	24/12/2024	Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2024)	
Parts: 143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKR3749D)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	965.50 FL	*965.50 FL
2	1		*REAR BOOT LID EMBLEM - ALTIS	Necessary	75.10 FL	*75.10 FL
3	1		*REAR BOOT LID EMBLEM - COROLLA	Necessary	87.20 FL	*87.20 FL
4	1		*REAR BOOT LID EMBLEM - LOGO	Necessary	65.70 FL	*65.70 FL
5	1		*REAR BOOT LID OUTER CHROME GARNISH	Serviceable	287.60 FL	*- FL
6	1		*REAR BOOT LID INNER LOCK	Dented	385.70 FL	*385.70 FL
7	1		*REAR BOOT LID INNER LOCK SENSOR	Cracked	187.60 FL	*187.60 FL
8	1		*REAR BOOT RUBBER (50%)	Dented / Cut	225.60 FN	*112.80 F
9	2		*REAR BOOT LID REFLECTOR	Serviceable	1,100.20 FL	*- FL
10	2		*REAR FENDER	Repair	2,298.40 FL	*- FL
11	2		*REAR FENDER INNERSHIELD	Serviceable	250.20 FL	*- FL
12	2		*REAR FENDER INNER TRIM	Serviceable	1,101.40 FL	*- FL
13	1		*REAR END PANEL	Bent	655.70 FL	*655.70 FL
14	1		*REAR END PANEL INNER GARNISH	Missing	263.70 FL	*263.70 FL
15	2		*REAR TAIL-LAMP ASSY	Cracked	1,251.20 FL	*1,251.20 FL
16	2		*REAR TAIL-LAMP PANEL	Repair	510.20 FL	*- FL
17	1		*REAR SPARE TYRE PANEL	Repair	1,150.60 FL	*- FL
18	1		*REAR SPARE TYRE COVER BOARD	Cracked	455.60 FL	*455.60 FL
19	1		*REAR BUMPER	Bent	654.80 FL	*654.80 FL
20	1		*REAR BUMPER REINFORCEMENT	Bent	487.60 FL	*487.60 FL
21	2		*REAR BUMPER BRACKET	Repair	310.20 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER	Distorted	170.20 FL	*170.20 FL
23	2		*REAR BUMPER REFLECTOR	Serviceable	176.70 FL	*- FL
24	1		*SET REAR REVERSE SENSOR	Dented	395.10 FN	*200.00 F
25	1		*REAR EXHAUST SILENCER	Repair	971.10 FL	*- FL
26	1		*FRONT BONNET	Repair	950.60 FL	*- FL
27	1		*FRONT BONNET LOCK	Repair	255.70 FL	*- FL
28	2		*FRONT HEADLAMP	Mtg Cracked	7,866.20 FL	*7,208.60 FL
29	1		*FRONT GRILLE	Mtg Cracked	753.20 FL	*694.30 FL
30	1		*FRONT GRILLE EMBLEM	Necessary	65.70 FL	*65.70 FL
31	1		*FRONT SUPPORT PANEL	Repair	1,136.30 FL	*- FL
32	1		*FRONT BRACE PANEL	Repair	125.60 FL	*- FL
33	1		*FRONT BUMPER	Cracked	659.30 FL	*659.30 FL
34	1		*FRONT BUMPER REINFORCEMENT	Repair	473.50 FL	*- FL
35	1		*FRONT BUMPER SPONGE	Cracked	135.70 FL	*135.70 FL
36	1		*FRONT BUMPER LOWER GRILLE	Serviceable	225.60 FL	*- FL
37	1		*AIR CON CONDENSER	Serviceable	1,984.30 FL	*- FL
38	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
39	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS
40	20		*CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$) 29,234.60 14,862.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,800.00	900.00
2	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION	New	1,800.00	1,200.00
3	CHECK / RECONNECT WIRING	New	45.00	40.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	60.00
5	REMOVE / RENEW REAR EXHAUST SILENCER	New	180.00	0.00
6	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
7	REMOVE / REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	0.00
8	REMOVE / REFIT ROOF LINING TO FACILITATE REPAIR	New	180.00	0.00
9	REMOVE / RENEW AIR CON CONDENSER AND TO TOP UP GAS	New	180.00	0.00
Gross Labour Cost (S\$)			4,635.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >