

M/S First Capital

Pr-20/12@403



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SLF 6561 J

Parts (a) Cost / List Price Items	\$ 8,387.07
Plus/Less 25%	\$ 2,096.77
Total of Cost / List	\$ 6,290.30
(b) Nett Price Items	
Less	
Total of Nett Item	
(c) Special Nett Items	
Total Parts Cost	
Labour	\$ 3,120.00
Total	\$ 9,410.30

Not authorized
1/12/24 @ 1700h
Picking up the car

The above total will be subjected to 9% G.S.T.

Name of Surveyor

Hennem

Company

LICK

Survey conducted on

24/12/24

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess

:\$

(e) Signature of surveyor

Date:

24/12/24

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SLF6561J**
Make & Model : **TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT**
Chassis No : **MR053REH104554290**

Submit By : **02-Sep-16**
Year Manufacture : **1ZRY313612**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$252.20		20052
2	Rear bumper	1	\$855.40		—
3	Rear bumper clip	10	\$60.00		—
4	Rear bumper side retainer LH	1	\$168.10		—
5	Rear bumper side retainer RH	1	\$168.10		X
6	Rear bumper bracket LH	1	\$94.10		7
7	Rear bumper bracket RH	1	\$94.10		X
8	Rear bumper sponge	1	NA		
9	Rear bumper reinforcement	1	\$615.60	5202302190	2
10	Rear bumper reflector LH	1	\$83.40		X
11	Rear bumper reflector RH	1	\$83.40		X
12	Bootlid	1	\$1,218.30		X
13	Bootlid lock	1	\$553.10		X
14	Bootlid hinge LH	1	\$96.30		X
15	Bootlid hinge RH	1	\$96.30		X
16	Bootlid emblem	1	\$61.70		X
17	Wording "COROLLA"	1	\$54.17		X
18	Wording "ALTIS"	1	\$51.60		X
19	Bootlid reflector LH	1	\$596.20		X
20	Bootlid reflector RH	1	\$596.20		X
21	Tail end panel	1	\$1,025.30		X
22	Tail end panel garnish	1	\$334.70		X
23	Tail end panel garnish clip	10	\$60.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
Make & Model :
Chassis No :

SLF6561J

TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT
MR053REH104554290

Submit By :
Year Manufacture :
Engine No. :
Cost / List

0
42615

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail lamp LH	1	\$584.40		X
25	Tail lamp RH	1	\$584.40		X
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SLF6561J** Submit By : **0**
Make & Model : **COROLLA ALTIS CLASSIC 1.6 C** Year of Manufacture : **42615**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,BOOTLID,END PANEL,LHR FENDER,RHR FENDER)	\$1,200.00	350/-
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,BOOTLID,END PANEL,LHR FENDER,RHR FENDER)	\$1,200.00	400/-
3	To check wiring	\$50.00	15/-
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
5	To tuff coat. <i>nn</i>	\$100.00	X
6	To transfer boot mechanism to new boot <i>nn</i>	\$150.00	X
7	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$150.00	X
8	To remove & refit reverse sensor	\$120.00	50/-

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.