

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24120348/TVP3M4**Date:** 19/03/2025REFERENCE

Insured/Claimant: NEO GLOBAL PTE. LTD. Policy No: MCF24B00000200
Date of Loss: 13/12/2024 Nature of Claim: OD Claim No: DMCF2400136H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE3030T**
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2561802
Reg. Date: 26/10/2015 (Man. Year: 2015) Chassis No: JTFAT35Y20K205228
Colour: White/Red Odometer: 346066 km
Engine Capacity: 2982 cc
Market Value/New Car Price: S\$15,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/R15 Rear Tyre Size: 155/R12 (D)
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6/6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,973.80	3,692.30	1,281.50	25.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	2,180.00	1,230.00	36.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,383.80	5,872.30	2,511.50	29.96
Approved Total (Overridden) (S\$)		4,650.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	8,383.80	4,050.00	4,333.80	51.69
+ GST 9.00/9.00% (S\$)	754.54	364.50	390.04	51.69
Nett Amount (S\$)	9,138.34	4,414.50	4,723.84	51.69

INSPECTION

Date of Assignment: 23/12/2024 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)
Date Inspected: 24/12/2024 Inspected At: BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Mar 2025)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3030T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
2	1		*FRT BUMPER (WCP)	Deformed	220.00 F	*220.00 F
3	1		*FRT BUMPER BRACKET (WCP)	Bent	100.00 F	*100.00 F
4	1		*FRT GRILLE (WCP)	Cracked	180.00 F	*180.00 F
5	1		*FRT GRILLE EMBLEM (WCP)	Necessary	45.00 F	*45.00 F
6	1		*FRT GRILLE TOP SEAL (WCP)	Necessary	48.00 F	*48.00 F
7	10		*FRT GRILLE CLIPS (+) (WCP)	Necessary	80.00 F	*80.00 F
8	10		*FRT GRILLE CLIPS (-) (WCP)	Not Necessary	80.00 F	*- F
9	2		*FRT HEADLAMP (WCP)	Cracked	680.00 F	*680.00 F
10	2		*FRT HEADLAMP LOWER SEAL (WCP)	Cut	50.00 F	*50.00 F
11	1		*FRT PANEL CPL (WCP)	Bent	1,200.00 F	*1,200.00 F
12	1		*FRT CORNER PANEL LH (WCP)	Bent	75.00 F	*75.00 F
13	1		*FRT PANEL CENTER GARNISH (WCP)	Cut	120.00 F	*120.00 F
14	1		*FRT PANEL SIDE GARNISH (WCP)	N/S Not Necessary/O/S Deformed	90.00 F	*45.00 F
15	1		*FRT WIPER GARNISH (WCP)	Bent	150.00 F	*150.00 F
16	1		*FRT WIPER GARNISH SIDE COVER (WCP)	N/S Not Necessary/ O/S Cracked	100.00 F	*50.00 F
17	2		*FRT WIPER ARM (WCP)	Not Necessary	140.00 F	*- F
18	2		*FRT WIPER ARM BLADE (WCP)	Not Necessary	50.00 F	*- F
19	2		*FRT WIPER NOZZLE (WCP)	Not Necessary	40.00 F	*- F
20	2		*FRT WIPER NOZZLE NUT (WCP)	Not Necessary	20.00 F	*- F
21	1		*FRT WIPER LINKAGE (WCP)	Not Necessary	160.00 F	*- F
22	1		*FRT SIDE MIRROR ARM LH (WCP)	Bent	200.00 F	*200.00 F
23	2		*FRT DOOR ROC STICKER	Cut	100.00 FS	*100.00 FS
24	1		*FRT AIRCON BLOWER ASSY (WCP)	Not Necessary	580.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,533.00	3,368.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	440.80	324.30
Total Parts (\$\$)	4,973.80	3,692.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT DOOR X 2 , FRT FLOOR PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New	1,400.00	1,000.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO DIAGNOSE AND RESET FAULT CODE	New	180.00	150.00
5	TO REMOVE & REFIX FRT DASHBOARD	New	280.00	0.00
6	TOP UP AIRCON GAS	New	100.00	0.00
Gross Labour Cost (\$\$)			3,410.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >