

ASS. REC. BY: Taufikh

REF:

CS/1CS24120348/Hvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. MCF24B00000200

Claims No. DMCF2400136H/CT

Sum Insured: _____ Excess: \$600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$15K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GRE3030T Yr Regn: 2015, 10Type: M.Car / M.Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyna c.c. 2982Colour White/Red A/C: Insured / Std / NI / NASp. Reading 346066 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT 353.20K205 228Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ S/Rim / STD A/Rim orTyre Size: F: 195/R15R: 155/R12BS / ☒ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/12/2024

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6/6 mmL/Bal. 6/6 mmD.O.I. 24/12/24Smy An Tee

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/3/25 Taufikh confirmed LS \$4650 (red 3733.80, 44%)

1

1

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email:

sngahtee@singnet.com.sg; darren@sngahtee.com; admin@sngahtee.com; admin2@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MCF24B00000200	Date of Loss:	13/12/2024
Vehicle Reg. No.:	GBE3030T	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NEO GLOBAL PTE. LTD.		
Driver:	SAW HENARY HTOO		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	26/10/2015
Vehicle Colour:	SILVER		
Engine No:	1KD2561802	Chassis No:	JTFAT35Y20K205228
Odometer:	2982 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Remarks:	VEHICLE AT WORKSHOP		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	4,973.80
Miscellaneous Items	0.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,383.80
+ GST 9.00% (\$\$)	754.54
Nett Amount (\$\$)	9,138.34

This claim is handled by: **JOYCE TAN LAI CHIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanfik 97495749
Not advise Ex \$600
L/S Resurvey after repair 7 days
tanfik e/kkauto.m

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Dec 2024)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt *25.00 FS
2	1		*FRT BUMPER	0.00	0.00	de *220.00 F
3	1		*FRT BUMPER BRACKET	0.00	0.00	bb *100.00 F
4	1		*FRT GRILLE	0.00	0.00	cur *180.00 F
5	1		*FRT GRILLE EMBLEM	0.00	0.00	ner *45.00 F
6	1		*FRT GRILLE TOP SEAL	0.00	0.00	ner *48.00 F
7	10		*FRT GRILLE CLIPS (+)	0.00	0.00	ner *80.00 F
8	10		*FRT GRILLE CLIPS (-)	0.00	0.00	ner *80.00 F
9	2		*FRT HEADLAMP	LH-? 0.00	0.00	RH cur *680.00 F
10	2		*FRT HEADLAMP LOWER SEAL	0.00	0.00	aut *50.00 F
11	1		*FRT PANEL CPL	0.00	0.00	bt *1,200.00 F
12	1		*FRT CORNER PANEL LH	0.00	0.00	bt *75.00 F
13	1		*FRT PANEL CENTER GARNISH	0.00	0.00	aut *120.00 F
14	2		*FRT PANEL SIDE GARNISH	LH-? 0.00	0.00	RH di *90.00 F
15	1		*FRT WIPER GARNISH	0.00	0.00	bt *150.00 F
16	2		*FRT WIPER GARNISH SIDE COVER	LH-? 0.00	0.00	RH cur *100.00 F
17	2		*FRT WIPER ARM	0.00	0.00	X *140.00 F
18	2		*FRT WIPER ARM BLADE	0.00	0.00	X *50.00 F
19	2		*FRT WIPER NOZZLE	0.00	0.00	X *40.00 F
20	2		*FRT WIPER NOZZLE NUT	0.00	0.00	X *20.00 F
21	1		*FRT WIPER LINKAGE	0.00	0.00	? *160.00 F
22	1		*FRT SIDE MIRROR ARM LH	0.00	0.00	bt *200.00 F
23	2		*FRT DOOR ROC STICKER	0	0.00	aut *100.00 FS
24	1		*FRT AIRCON BLOWER ASSY	0.00	0.00	? *580.00 F

F=Franchise part, S=SpcNett.

Sub Total (\$)	4,533.00
+ Margin on L,N Items 10.00% (\$)	440.80
Total Parts (\$)	4,973.80

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK FRT DOOR X 2 , FRT FLOOR PANEL,WELD,REMOVE & REPLACE ABOVE PARTS	New 1000	1,400.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New 1000	1,400.00
3	TO CHECK WIRING	New 30	50.00
4	TO DIAGNOSE AND RESET FAULT CODE	New 150	180.00
5	TO REMOVE & REFIX FRT DASHBOARD	New 200?	280.00
6	TOP UP AIRCON GAS	New ?	100.00
Gross Labour Cost (\$\$)			3,410.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE3030T/18/12/2024 17:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	351N
Vehicle Details	
Vehicle No.:	GBE3030T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2561802
Chassis No.:	JTFAT35Y20K205228
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,002.00
COE Rebate Amount:	\$4,287.00
Total Rebate Amount:	\$4,287.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 16 Dec 2024

OK