

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG24120350/UVP3E2
Date: 07/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230101735
Claimant Vehicle No :	SLQ8069T	Insured Vehicle No :	SMF464J
Date of Loss:	21/12/2024	Nature of Claim:	TP
		Claim No:	5795734227SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8069T	Engine No:	LEB5950592
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31250576
Reg. Date:	24/07/2017 (Man. Year: 2017)	Odometer:	99422 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,135.60	6,301.52	4,834.08	43.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,039.00	2,450.00	589.00	19.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,174.60	8,751.52	5,423.08	38.26
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	14,174.60	7,000.00	7,174.60	50.62

INSPECTION

Date of Assignment:	23/12/2024	JC Motor Consultancy (Kaki Bukit)
Date Inspected:	24/12/2024	Inspected At: 1 Kaki Bukit Ave 6, #01-96 Autobay @Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,287.10 FL	*1,099.20 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	121.60 FL	*121.60 FL
3	1		*TAILGATE OUTER GARNISH	Not Necessary	391.40 FL	*- FL
4	1		*TAILGATE LOGO	Not Necessary	58.60 FL	*- FL
5	1		*TAILGATE EMBLEM VEZEL	Necessary	86.90 FL	*86.90 FL
6	1		*TAILGATE LAMPS - L/R	N/S Cut / O/S Not Necessary	940.60 FL	*368.20 FL
7	2		*TAILGATE LICENCE LAMPS	Not Necessary	162.40 FL	*- FL
8	1		*TAILGATE INNER LOCK	Twisted	280.60 FL	*280.60 FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	486.90 FL	*486.90 FL
10	1		*TAILGATE W/STRIP	Torn	191.60 FL	*191.60 FL
11	2		*TAILGATE DAMPERS - L/R	Not Necessary	280.40 FL	*- FL
12	2		*TAILGATE STOPPERS	Not Necessary	25.20 FL	*- FL
13	1		*TAILLAMPS - L/R	N/S Cracked/O/S NotNecessary	1,040.20 FL	*520.10 FL
14	1		*REAR BUMPER	Distorted	991.60 FL	*762.00 FL
15	1		*REAR BUMPER SIDES - L/R	N/S Deformed/O/S NotNecessary	483.20 FL	*241.60 FL
16	1		*REAR BUMPER SIDE RETAINERS - L/R	O/S Cracked	179.20 FL	*89.60 FL
17	1		*REAR BUMPER REFLECTOR - LH	Cracked	110.20 FL	*110.20 FL
18	1		*REAR END PANEL	Badly Dented	759.10 FL	*615.00 FL
19	1		*REAR END PANEL TRIM	Twisted	182.60 FL	*182.60 FL
20	1		*REAR FLOOR BOARD	Deformed / Torn	380.60 FL	*380.60 FL
21	1		*REAR FLOOR SPONGE TRAY	Serviceable	360.90 FL	*- FL
22	1		*REAR FLOOR PANEL	Crumpled / Buckled	781.60 FL	*781.60 FL
23	1		*REAR FLOOR PANEL UNDERCOVER	Deformed / Torn	261.90 FL	*261.90 FL
24	1		*REAR FENDER - LH	Repair	931.60 FL	*- FL
25	1		*REAR FENDER ARC GARNISHES - L/R	N/S Torn	763.20 FL	*280.40 FL
26	1		*REAR FENDER INNER TRIM BOARD - LH	Deformed / Torn	651.90 FL	*488.20 FL
27	1		*REAR FENDER INNER SHIELD - LH	Not Necessary	181.60 FL	*- FL
28	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	181.20 FL	*- FL
29	1		*REAR SMART KEYLESS BUZZLE	Cracked	190.60 FL	*190.60 FL
30	1		*SET TAILGATE SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*SET TAILGATE TOP SPOILER CLIP	Not Necessary	80.00 FS	*- FS
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	1		*SET REAR REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
34	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,684.50	7,809.40
- List Item Discount on L Items 20.00/20.00% (\$)	2,548.90	1,507.88
Total Parts (\$)	11,135.60	6,301.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	120.00
2	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	159.00	60.00
4	TO REMOVE, REFIX REAR REVERSE SENSOR / CAMERA	New	80.00	30.00
5	TO RESPRAY UNDERCOATING	New	100.00	80.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	1,100.00
7	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,200.00	1,000.00
Gross Labour Cost (\$)			3,039.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >