



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNP 4222A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR FENDER RH	DENTED	1,985.20	1,985.20
1	REAR FENDER INNER COWLING RH	NOT NECESSARY	260.80	-
1	REAR FENDER RAILWAY COVER GARNISH RH	NOT NECESSARY	439.20	-
1	REAR FENDER INNERTRIM RH	NOT NECESSARY	798.10	-
1	REAR TAILLAMP RH	CUT	944.30	650.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,480.20	-
1	REAR BUMPER SENSOR	NOT NECESSARY	278.50	-
1	REAR BUMPER RETAINER RH (FRONT)	NOT NECESSARY	120.50	-
1	REAR BUMPER RETAINER RH (REAR)	NOT NECESSARY	155.30	-
1	REAR BUMPER CHROME RH	NOT NECESSARY	289.70	-
1	REAR WHEELHUB BEARING RH	NOT NECESSARY	425.80	-
1	REAR ABSORBER RH	NOT NECESSARY	438.70	-
	LESS 20% DISCOUNT		-1,523.26	-527.04
			6,093.04	2,108.16
1	REAR RIM RH (SN)	CUT	1,233.40	500.00
	LESS 20% DISCOUNT		-246.68	-
			986.72	500.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR FENDER GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	TYRE (SN)	NOT NECESSARY	350.00	-
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNERCOWLING CLIPS (SN)	NOT NECESSARY	30.00	-
			470.00	40.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,000.00	500.00
	SPRAY PAINTING.		1,000.00	500.00
	ANTI RUST.		100.00	60.00

Report Ref No. CS/INC24120351/Anh3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL FENDER GLASS.		120.00	40.00
	TO PERFORM COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO PERFORM COMPUTER RESET AND APDAT.	NOT NECESSARY	350.00	-
	REMOVE AND INSTALL INTERIOR UPHOLSTERY.		150.00	60.00
	REMOVE AND INSTALL REVERSE SENSOR.	NOT NECESSARY	120.00	-
			2,960.00	1,160.00
	<b>GRAND TOTAL</b>		<b>10,509.76</b>	<b>3,808.16</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,000.00</b>

Report Ref No. CS/INC24120351/Anh3m4(N)

TOTAL FOR SPARE PARTS: \$ 7,549.76 \$ 2,648.16

TOTAL FOR LABOUR : \$ 2,960.00 \$ 1,160.00

TOTAL REPAIR COST: \$10,509.76 \$ 3,808.16

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.