



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 5850R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	DENTED/BENT	1,218.40	1,218.40
1	FRONT DOOR HINGE (BOTTOM)	NOT NECESSARY	131.70	-
1	FRONT DOOR LOWER STEP GARNISH RH	GRAZED	281.75	281.75
1	FRONT DOOR WEATHERSTRIPE	NOT NECESSARY	219.00	-
1	FRONT BUMPER	BENT	356.65	356.65
1	HEAD LAMP RH	CRACKED	789.10	789.10
	LESS 25% DISCOUNT		-749.15	-661.47
			2,247.45	1,984.43
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR R.O.C STICKER (SN)	NECESSARY	40.00	30.00
			40.00	30.00
<u>LABOUR</u>				
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO REMOVE & REFIX FRONT RH DOOR MECHANISM.		250.00	50.00
	TO RESPRAY AFFECTED AREAS.		600.00	500.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS.		600.00	420.00
			1,500.00	990.00
GRAND TOTAL			3,787.45	3,004.43
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/LIP24120352/Uvh3m4(N)

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,050.00=NETT VALUE: \$3,950.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.