



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |  |            |
|--|--|--|------------|
| LIBERTY INSURANCE PTE LTD<br>ONE RAFFLES QUAY #25-01<br>NORTH TOWER SINGAPORE 048583<br>ATTN: ANDY SEAH  |  | Ref: CS/LIP24120354/Uqh3e2(N)<br>Date: 15/01/2025<br>Code: LIP |            |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |  |            |
| Insured Veh.   | SKQ 7432X  | Veh. Inspected   | SMA 5606K  |
| Policy No.   |  | Coverage (\$)  | 0.00       |
| Claim No.  | AVS24/3980   | Excess (\$)  | 0.00       |
| Assign From  | ANDY SEAH  | Assign Date  | 23/12/2024 |
| 2. Vehicle Particulars & Condition   |  |  |            |
| Make & Model   | HONDA JAZZ 1.5 (A)   | c.c  | 1498       |
| Engine No.   | HIDDEN   | Year of Reg.   |            |
| Chassis No.  | JHMGK5850JX204260  | Colour   | MAROON     |
| Odometer   | 60967 KM   | Steering   | IN ORDER   |
| Brakes   | IN ORDER   | Modification   | SPORTS RIM |
| General  | GOOD   |  |            |
| 3. Conditions of Tyres   |  |  |            |
|  | Size   | Make   | Balance    |
| R/H Front Tyre   | 185/55 R16   | DUNLOP   | 6 mm       |
| L/H Front Tyre   | 185/55 R16   | DUNLOP   | 6 mm       |
| R/H Rear Tyre  | 185/55 R16   | DUNLOP   | 6 mm       |
| L/H Rear Tyre  | 185/55 R16   | DUNLOP   | 6 mm       |
| 4. Description of Damages  |  |  |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |  |            |
| 5. General Information   |  |  |            |
| Accident Date  | 21/12/2024   | Inspection Date  | 24/12/2024 |
| Survey held at   | LEANG AUTOMOTIVE<br>BLK 1 KAKI BUKIT AVE 6<br>#01-68 AUTOBAY@ KAKI BUKIT<br>SINGAPORE 417883 |  |            |
| 5a. Remarks  |  |  |            |
| A)REGISTRATION DATE: 12 JUN 2018<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |  |            |
| 5b. Estimate Days of Repair  |  |  |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 5 Working Days   |            |