

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

Our File No:

CS/AIG24120360/ANP3E2  

Date:

30/04/2025

|                   |                                |                  |            |                        |
|-------------------|--------------------------------|------------------|------------|------------------------|
| REFERENCE         |                                |                  |            |                        |
| Insured/Claimant: | TEO KIM SHENG (ZHANG JINSHENG) | Policy No:       | 7240297885 |                        |
| Date of Loss:     | 22/12/2024                     | Nature of Claim: | OD         | Claim No: 7339956147SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                |             |                   |
|-----------------------------|--------------------------------|-------------|-------------------|
| Reg No:                     | SNU6328P                       |             |                   |
| Make & Model:               | XPENG G6, RWD (LONG RANGE) (A) | Engine No:  | HIDDEN            |
| Reg. Date:                  | 16/12/2024 (Man. Year: 2024)   | Chassis No: | L1NNSGHA0RB093135 |
| Colour:                     | White                          | Odometer:   | 185 km            |
| Engine Capacity:            | 0 cc                           |             |                   |
| Market Value/New Car Price: | S\$203,000.00                  |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price     |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|  |                  |                  |                  |
|--|------------------|------------------|------------------|
| Front Tyre Size:   | 255/45 R20       | Rear Tyre Size:  | 255/45 R20       |
| Front Left Side:   | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side:  | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |
| The above values represent the remaining tyre treads depth |                  |                  |                  |

| COST OF CLAIMS                | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------|------------|------------|--------|
| Parts                         | 13,617.00  | 8,888.00   | 4,729.00   | 34.73  |
| Miscellaneous Items           | 0.00       | 0.00       | 0.00       |        |
| Labour                        | 12,000.00  | 8,600.00   | 3,400.00   | 28.33  |
| Paintwork Labour              | 0.00       | 0.00       | 0.00       |        |
| Towing                        | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (\$\$) | 25,617.00  | 17,488.00  | 8,129.00   | 31.73  |
| - Excess (\$\$)               | 4,200.00   | 4,200.00   | 0.00       | 0.00   |
| (\$\$)                        | 21,417.00  | 13,288.00  | 8,129.00   | 37.96  |
| + GST 9.00/9.00% (\$\$)       | 1,927.53   | 1,195.92   | 731.61     | 37.96  |
| Nett Amount (\$\$)            | 23,344.53  | 14,483.92  | 8,860.61   | 37.96  |

INSPECTION

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 24/12/2024 |               |  |
| Date Inspected:             | 27/12/2024 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 7.0 days   |               |  |

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



(FOR MANDATE ONLY)

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's               | Amount           |
|-----|-----|----------|----------------------------------|---------------|--------------------------|------------------|
| 1   | 1   |          | *FRONT BUMPER                    | Torn          | 773.00 FS                | *618.40 FS       |
| 2   | 1   |          | *FRONT BUMPER LOWER SPOILER      | Deformed      | 26.00 FS                 | *20.80 FS        |
| 3   | 1   |          | *FRONT PARKING AID SENSOR        | Not Necessary | 80.00 FS                 | *- FS            |
| 4   | 1   |          | *FRONT BUMPER SIDE GUIDE - RH    | Not Necessary | 2.00 FS                  | *- FS            |
| 5   | 1   |          | *FRONT BUMPER TRIM - RH          | Cut           | 29.00 FS                 | *23.20 FS        |
| 6   | 1   |          | *FRONT DAYLIGHT - RH             | Not Necessary | 1,927.00 FS              | *- FS            |
| 7   | 1   |          | *HEADLIGHT - RH                  | Cracked       | 8,329.00 FS              | *6,663.20 FS     |
| 8   | 2   |          | *FRONT WHEEL ARCH TRIM - LH / RH | Necessary     | 652.00 FS                | *521.60 FS       |
| 9   | 1   |          | *FRONT BUMPER LOWER COVER        | Cracked       | 63.00 FS                 | *50.40 FS        |
| 10  | 1   |          | *SUNDRIES                        | Necessary     | 500.00 FS                | *1.60 FS         |
| 11  | 1   |          | *FRONT BUMPER LOWER GRILLE       | Cracked       | 256.00 FS                | *204.80 FS       |
| 12  | 1   |          | *FRONT LOCK CARRIER              | Cracked       | 713.00 FS                | *570.40 FS       |
|     |     |          | (Supplementary)                  |               |                          |                  |
| 13  | 1   |          | *FRONT WHEEL HOUSING LINER RHS   | Torn          | 127.00 FS                | *101.60 FS       |
|     |     |          | (Supplementary)                  |               |                          |                  |
| 14  | 1   |          | *FRONT FOG LAMP COVER            | Deformed      | 5.00 FS                  | *4.00 FS         |
|     |     |          | (Supplementary)                  |               |                          |                  |
| 15  | 1   |          | *READY MIX COOLANT 4L            | Necessary     | 135.00 FS                | *108.00 FS       |
|     |     |          | (Supplementary)                  |               |                          |                  |
|     |     |          |                                  |               | <b>Total Parts (S\$)</b> | <b>13,617.00</b> |
|     |     |          |                                  |               |                          | <b>8,888.00</b>  |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars   | Lab.Type | Repairer's       | Amount          |
|-------------------------------|---|----------|------------------|-----------------|
| <b>Labour Items</b>           |   |          |                  |                 |
| 1                             | TO CARRY OUT DE-ENERGIZE HIGH VOLTAGE SYSTEM. DEACTIVATION AND ACTIVATION   | New      | 480.00           | 480.00          |
| 2                             | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New      | 480.00           | 480.00          |
| 3                             | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE  | New      | 600.00           | 300.00          |
| 4                             | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED                       | New      | 2,200.00         | 600.00          |
| 5                             | TO RESPRAY FRONT BUMPER AND BOTH FRONT WHEEL ARCH TRIMS   | New      | 2,300.00         | 1,050.00        |
| 6                             | TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM   | New      | 800.00           | 800.00          |
| 7                             | TO PROVIDE PAINT PROTECTION FILM FOR AFFECTED AREA  | New      | 1,360.00         | 1,360.00        |
| 8                             | TO CARRY OUT DIAGNOSTIC CHECK   | New      | 480.00           | 480.00          |
| 9                             | TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR<br>CHECK ELECTRICAL<br>(Supplementary)  | New      | 1,800.00         | 1,800.00        |
| 10                            | TO RENEW LOCK CARRIER AND ALIGN TO POSITION<br>(Supplementary)  | New      | 1,500.00         | 1,250.00        |
| <b>Gross Labour Cost (\$)</b> |   |          | <b>12,000.00</b> | <b>8,600.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >