

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24120362/EVP3E2  
**Date:** 23/01/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
<b>Claimant Vehicle No :</b>	SMA4830K	<b>Insured Vehicle No :</b>	SKT9011Z
Date of Loss:	14/12/2024	Nature of Claim:	TP
		Claim No:	DMPC2401738H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMA4830K</b>	Engine No:	8ARZ118849
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Chassis No:	JTEZB3GH00J001945
Reg. Date:	30/04/2018 (Man. Year: 2018)	Odometer:	108801 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,556.00	586.00	9,970.00	94.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	500.00	2,400.00	82.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,456.00</b>	<b>1,086.00</b>	<b>12,370.00</b>	<b>91.93</b>
<b>+ GST 9.00/9.00% (S\$)</b>	1,211.04	97.74	1,113.30	91.93
<b>Nett Amount (S\$)</b>	<b>14,667.04</b>	<b>1,183.74</b>	<b>13,483.30</b>	<b>91.93</b>

INSPECTION

Date of Assignment:	24/12/2024	
Date Inspected:	27/12/2024	Inspected At: Century Motors (Singapore) Pte Ltd (HQ) 6 Marsiling Lane, Singapore 739145
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jan 2025)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA4830K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRT BUMPER</b> (WCP)	Deformed	360.00 F	*360.00 F
2	1		<b>*FRT BUMPER BRKT RH</b> (WCP)	Not Necessary	50.00 F	*- F
3	1		<b>*FRT BUMPER BRKT LH</b> (WCP)	Not Necessary	50.00 F	*- F
4	1		<b>*HEADLAMP RH</b> (WCP)	Not Necessary	2,500.00 F	*- F
5	1		<b>*HEADLAMP LH</b> (WCP)	Not Necessary	2,500.00 F	*- F
6	1		<b>*HEADLAMP BRKT RH</b> (WCP)	Not Necessary	50.00 F	*- F
7	1		<b>*HEADLAMP BRKT LH</b> (WCP)	Not Necessary	50.00 F	*- F
8	1		<b>*FRT GRILLE ASSY</b> (WCP)	Not Necessary	400.00 F	*- F
9	1		<b>*FRT LOWER GRILLE ASSY</b> (WCP)	Not Necessary	280.00 F	*- F
10	1		<b>*FRT TOWING COVER</b> (WCP)	Not Necessary	30.00 F	*- F
11	1		<b>*FRT LOWER DIFFUSER</b> (WCP)	Not Necessary	280.00 F	*- F
12	1		<b>*FRT FOG LAMP RH</b> (WCP)	Not Necessary	160.00 F	*- F
13	1		<b>*FRT FOG LAMP LH</b> (WCP)	Not Necessary	160.00 F	*- F
14	1		<b>*FRT SPOUNGE</b> (WCP)	Not Necessary	150.00 F	*- F
15	1		<b>*FRT REINFORCEMENT</b> (WCP)	Not Necessary	280.00 F	*- F
16	1		<b>*FRT SUPPORT PANEL</b> (WCP)	Not Necessary	500.00 F	*- F
17	1		<b>*CONDENSER</b> (WCP)	Not Necessary	650.00 F	*- F
18	1		<b>*RADIATOR</b> (WCP)	Not Necessary	690.00 F	*- F
19	1		<b>*FRT PARKING SENSOR</b> (WCP)	Not Necessary	220.00 F	*- F
20	1		<b>*AIRCON GAS</b>	Necessary	120.00 FS	*120.00 FS
21	1		<b>*COOLANT</b>	Not Necessary	60.00 FS	*- FS
22	1		<b>*FRT BUMPER CLIPS</b>	Necessary	40.00 FS	*30.00 FS
23	1		<b>*FRT NUMBER PLATE AND HOLDER</b>	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>9,620.00</b>	<b>550.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	936.00	36.00
<b>Total Parts (\$\$)</b>	<b>10,556.00</b>	<b>586.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE TO REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT PARTS	New	1,400.00	250.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,000.00	220.00
3	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	150.00	0.00
4	LABOUR TO REPAIR FRT BOTH SIDE FENDER	New	200.00	0.00
5	LABOUR TO ADJUST AND RESET FRT PARKING SENSOR	New	150.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,900.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >