



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: LIM SERENE

Ref: CS/INC24120363/Avh3e2(N)

Date: 25/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 3132X	Veh. Inspected	SMK 4104X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305827-002	Excess (\$)	0.00
Assign From	LIM SERENE	Assign Date	24/12/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP51335614	Colour	BLUE
Odometer	449026 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	KAPSEN	6 mm
L/H Front Tyre	185/60 R15	KAPSEN	6 mm
R/H Rear Tyre	185/60 R15	KAPSEN	6 mm
L/H Rear Tyre	185/60 R15	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/11/2024	Inspect Date / Time	24/12/2024 (12:50 PM)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**