

REF:

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MV

To In: _____ Vehicle No: _____

at V/O: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDKIIM Yr Regn: 2018, SeptType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jaguar XE C.D. 1998Colour: Red A/C: Insured / Std / NI / NASp. Reading: 103423 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJA B4AX4 JCP 36426Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim orTyre Size: F: 225/45R18R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 26/12/24Survey held at Ryder

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

COE Expiry :

Estimate given during : Yes (✓)

1st Survey : No ()

MV : 74KPV : 39.7KNett: 34.3K3606

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Form 1st:

Report Form 2nd:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

ESTIMATE OF REPAIR

Veh# : SDK11M

Model: JAGUAR XE
(28/9/2018 - 27/9/2028)

Accident Date : 11/12/2024

Location : RIVERVALE LINK

3P: SHD7040Y (1ST CAP)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front wheel rim LH <i>cut</i>		1800.00	1000/500
2	1 pc	Front bearing LH <i>new</i>	600.70	+	
3	1 pc	Front Lh tyre <i>new</i>		450.00	+
4	1 pc	Front headlamp Lh <i>Replaced</i>	5200.00	2	
5	1 pc	Front headlamp lower bracket RH <i>new</i>	145.40	+	
6	1 pc	Front headlamp sponge RH <i>new</i>	63.80	+	
7	1 pc	Front bumper <i>Replaced</i>	2340.20		
8	1 pc	Front bumper side retainer L <i>new</i>	286.20	+	
9	1 set	Front bumper clip <i>new</i>		50.00	✓
10	1 pc	Front fender Lh <i>Repair</i>	1587.00	+	
11	1 pc	Front fender inner shield clip RH <i>new</i>		50.00	+
Sub Total:			10,223.30	2,350.00	0.00
			10%	0%	0%
After Less %:			9,200.97	2,350.00	0.00
Labour					
1		To remove & refix accident damaged parts & realign accident affected area.		800.00	400
2		To spray paint on accident affected area.		800.00	400
3		Alignment		120.00	80
4		To check wiring & rewire parking sensor.		80.00	50
5		To diagnosis & reset after work.		400.00	+
Sub Total:				2,200.00	
Total:				13,750.97	
After less 20%:				11,000.78	

LKK Auto Services Pte Ltd
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Chief Estimator
Director
Signature: _____
DipEng, AAE(MIM), MSAE(Aust)
Date: _____

Adrian Lim
1/5 26/12/24
03 Days



8778 1999
24 hr accident call

