

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24120371/AQP3E2
Date: 19/12/2025REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLD9045Z	Insured Vehicle No :	SMS4688K
Date of Loss:	19/12/2024	Nature of Claim:	TP
		Claim No:	DMPC2401760H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9045Z	Engine No:	27195231067831
Make & Model:	MERCEDES-BENZ C180K, 1.8 (A)	Chassis No:	WDD2040462A157360
Reg. Date:	11/07/2008 (Man. Year: 2008)	Odometer:	273108 km
Colour:	Purple		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,037.33	15,563.10	26,474.23	62.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,350.00	2,020.00	5,330.00	72.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,387.33	17,583.10	31,804.23	64.40
Approved Total (Overridden) (S\$)		14,050.00		
(S\$)	49,387.33	14,050.00	35,337.33	71.55
+ GST 9.00/9.00% (S\$)	4,444.86	1,264.50	3,180.36	71.55
Nett Amount (S\$)	53,832.19	15,314.50	38,517.69	71.55

INSPECTION

Date of Assignment:	23/12/2024	
Date Inspected:	24/12/2024	Inspected At: JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2025)
Parts:	143	MERCEDES-BENZ C180K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD9045Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	274.00 FL	*- FL
2	2		*FRONT BUMPER LOWER BRACKET	Not Necessary	196.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	799.00 FL	*799.00 FL
4	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	374.00 FL	*- FL
5	2		*FRONT BUMPER REINFORCEMENT SIDE SUPPORT BRACKET	Not Necessary	188.00 FL	*- FL
6	2		*FRONT FENDER INNER COWLING	Torn	318.00 FL	*318.00 FL
7	1		*FRONT HEADLAMP	O/S Cracked	2,144.00 FL	*1,072.00 FL
8	2		*FRONT HEADLAMP PANEL	Bent	468.00 FL	*234.00 FL
9	1		*FRONT HEADLAMP PANEL TOP GARNISH	O/S Torn	348.00 FL	*174.00 FL
10	1		*BONNET LOGO	Necessary	68.00 FL	*68.00 FL
11	2		*BONNET HINGE	Not Necessary	174.00 FL	*- FL
12	2		*BONNET BOTTOM LOCK	Not Necessary	296.00 FL	*- FL
13	2		*BONNET STOPPER	Not Necessary	38.00 FL	*- FL
14	1		*FRONT RADIATOR TOP PANEL	Not Necessary	1,217.00 FL	*- FL
15	1		*FRONT RADIATOR TOP PANEL GARNISH	Cracked	190.00 FL	*190.00 FL
16	2		*FRONT RADIATOR SUPPORT STAND PANEL	Not Necessary	356.00 FL	*- FL
17	1		*FRONT TURBO COOLER	Not Necessary	1,726.00 FL	*- FL
18	1		*FRONT TURBO COOLER HOSE	Not Necessary	203.00 FL	*- FL
19	1		*AIR DUCT	Not Necessary	87.00 FL	*- FL
20	1		*RADIATOR	Not Necessary	1,342.00 FL	*- FL
21	1		*POWER STEERING OIL COOLER	Not Necessary	747.00 FL	*- FL
22	1		*WIPER TANK	Not Necessary	149.00 FL	*- FL
23	2		*AIRCON CONDENSER SIDE AIR GUARD	Not Necessary	172.00 FL	*- FL
24	1		*AIRCON CONDENSER	Damaged	1,282.00 FL	*1,282.00 FL
25	1		*AIRCON HOSE	Not Necessary	496.00 FL	*- FL
26	1		*COOLER AIR GUARD	Not Necessary	72.00 FL	*- FL
27	2		*COOLER AIR PIPE	Not Necessary	314.00 FL	*- FL
28	1		*FRONT ABS SENSOR RH	Not Necessary	386.10 FL	*- FL
29	1		*FRONT KNUCKLE ARM RH	Damaged	770.00 FL	*770.00 FL
30	1		*FRONT WHEEL HUP WITH BEARING RH	Damaged	460.00 FL	*460.00 FL
31	1		*FRONT SHOCK ABSORBER RH	Bent	672.00 FL	*672.00 FL
32	1		*FRONT LOWER ARM RH (FRONT)	Bent	774.00 FL	*774.00 FL
33	1		*FRONT LOWER ARM RH (REAR)	Bent	699.00 FL	*699.00 FL
34	1		*FRONT STABILIZER LINKAGE RH	Not Necessary	168.00 FL	*- FL
35	1		*FRONT STEERING RACK & PINION	Bent	3,947.00 FL	*3,947.00 FL
36	1		*FRONT CROSS MEMBER	Not Necessary	3,852.00 FL	*- FL
37	1		*FRONT CROSS MEMBER BOTTOM COVER	Not Necessary	588.20 FL	*- FL
38	2		*HEAD REST	Not Necessary	2,853.84 FL	*- FL
39	1		*FRONT BUMPER (SPECIAL TYPE)	Distorted	3,200.00 FS	*1,800.00 FS
40	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
41	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
42	1		*SET FRONT FENDER (SPECIAL TYPE)	Torn	2,000.00 FS	*1,200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
44	1		*SET FRONT RADIATOR TOP PANEL GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
45	1		*BONNET (SPECIAL TYPE)	Repair	2,800.00 FS	*- FS
46	1		*SET SIDE SKIRT (SPECIAL TYPE)	Not Necessary	2,000.00 FS	*- FS
47	1		*SIDE SKIRT CLIP RH	Not Necessary	50.00 FS	*- FS
48	1		*WHEEL RIM RH	Cut	1,800.00 FS	*900.00 FS
49	1		*WHEEL TYRE RH	Punctured	680.00 FS	*250.00 FS
50	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS
51	1		*RADIATOR COOLANT	Not Necessary	180.00 FS	*- FS
52	1		*STICKER WRAPPING (SPECIAL TYPE)	Necessary	2,800.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	44,958.14	16,709.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,920.81	1,145.90
Total Parts (\$\$)	42,037.33	15,563.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	2,000.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	RESET HEAD REST	New	650.00	0.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	REMOVE AND REFIX TURBO COOLER	New	80.00	0.00
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	300.00
9	WIRING CHECK	New	250.00	30.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	FOUR WHEEL ALIGNMENT	New	120.00	80.00
12	RESET ABS LIGHT	New	600.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	800.00	150.00
Gross Labour Cost (\$)			7,350.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >