

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24120372/EQP3M4(N)**Date:** 06/01/2025**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS001328
Claimant Vehicle No :	SHB6636X	Insured Vehicle No :	GBD6316E
Date of Loss:	23/12/2024	Nature of Claim:	TP
		Claim No:	M2407519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6636X		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU211008
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU146277
Colour:	Blue	Odometer:	733826 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,447.08	796.12	650.96	44.98
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,120.00	680.00	440.00	39.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,579.08	1,488.12	1,090.96	42.30
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,579.08	1,200.00	1,379.08	53.47
+ GST 9.00/9.00% (S\$)	232.12	108.00	124.12	53.47
Nett Amount (S\$)	2,811.20	1,308.00	1,503.20	53.47

INSPECTION

Date of Assignment:	26/12/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	26/12/2024	Inspected At:	
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Jan 2025)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6636X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER LOWER MOULDING	Broken	451.25 FL	*451.25 FL
3	1		*REAR REINFORCEMENT	Not Necessary	394.80 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER REINFORCEMENT STAY LH	Not Necessary	138.10 FL	*- FL
6	1		*REAR BUMPER BRACKET LH	Not Necessary	55.80 FL	*- FL
7	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
8	1		*REAR REVERSE SENSOR MAT	Not Necessary	180.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	1,751.35 982.65
					- List Item Discount on L Items 20.00/20.00% (\$\$)	304.27 186.53
					Total Parts (\$\$)	1,447.08 796.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	760.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	20.00
Gross Labour Cost (\$\$)			1,120.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >