

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24120375/EPA3Q2
Date: 18/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_03
Claimant Vehicle No : SGJ3932E Insured Vehicle No : SNH3335G
Date of Loss: 23/12/2024 Nature of Claim: TP Claim No: MFL2024D0015236

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGJ3932E
Make & Model: TOYOTA PRIUS, 1.8 PLUS (A) Engine No: 2ZR2F84481
Reg. Date: 16/11/2020 (Man. Year: 2019) Chassis No: JTDZS3EU00J052480
Colour: Black Odometer: 71465 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50ZR17 Rear Tyre Size: 225/50ZR17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,056.90	6,815.20	6,241.70	47.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,266.64	5,244.64	6,022.00	53.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,323.54	12,059.84	12,263.70	50.42
+ GST 9.00/9.00% (S\$)	2,189.12	1,085.39	1,103.73	50.42
Nett Amount (S\$)	26,512.66	13,145.23	13,367.43	50.42
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		13,707.41		

INSPECTION

Date of Assignment: 03/01/2025
Date Inspected: 03/01/2025 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2025)
Parts:	144	TOYOTA PRIUS 1.8 PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ3932E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER	Dented	855.40 F	*855.40 F
2	1		*PIECE, RR BUMPER	Necessary	58.00 F	*58.00 F
3	1		*RETAINER, RR BUMPER	Not Necessary	89.90 F	*- F
4	1		*RETAINER, RR BUMPER	Not Necessary	89.90 F	*- F
5	1		*SUPPORT, RR BUMPER	Not Necessary	217.70 F	*- F
6	1		*SUPPORT, RR BUMPER	Not Necessary	217.70 F	*- F
7	1		*REINFORCEMENT	Bent	334.00 F	*334.00 F
8	1		*ARM SUB-ASSY, RR	Bent	243.00 F	*243.00 F
9	1		*ARM SUB-ASSY, RR	Bent	243.00 F	*243.00 F
10	1		*PANEL SUB-ASSY, BODY	Not Necessary	1,058.90 F	*- F
11	1		*PLATE, BACK DOOR	Not Necessary	251.40 F	*- F
12	1		*PANEL SUB-ASSY, BACK	Dented	1,692.80 F	*1,692.80 F
13	1		*WEATHERSTRIP, BACK	Not Necessary	509.90 F	*- F
14	1		*GLASS SUB-ASSY, BACK	Necessary	1,426.00 F	*1,426.00 F
15	1		*DAM, WINDOW GLASS	Necessary	40.10 F	*40.10 F
16	1		*BOARD ASSY, BACK	Not Necessary	455.40 F	*- F
17	1		*LOCK ASSY, BACK DOOR	Not Necessary	571.00 F	*- F
18	1		*EMBLEM ASSY	Not Necessary	87.90 F	*- F
19	1		*PLATE, BACK DOOR	Necessary	87.90 F	*87.90 F
20	1		*PLATE, LUGGAGE COMPT	Necessary	75.70 F	*75.70 F
21	1		*GARNISH SUB-ASSY	Not Necessary	599.80 F	*- F
22	1		*SPOILER, RR N0.1	Cut	1,175.80 F	*1,175.80 F
23	1		*LENS & BODY, RR	Not Necessary	1,069.50 F	*- F
24	1		*LENS & BODY, RR	Not Necessary	1,022.70 F	*- F
25	1		*SIKA 182010 SIKA TACK GO!	Necessary	216.00 F	*216.00 F
26	1		*SIKA 207. G + P ADHESIVE PRIMER	Necessary	200.00 F	*200.00 F
27	1		*BACK SENSOR 218 ATTITUDE BLACK	Shorted	167.50 F	*167.50 F

F=Franchise part.

Total Parts (S\$)	13,056.90	6,815.20
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRY	New	100.00	50.00
2	SUPPLY SEALANT.	New	200.00	100.00
3	TO REPLACE AND REPAIR ACCIDENT DAMAGED PARTS.	New	4,752.00	1,584.00
4	TO RESPRAY ALL ACCIDENT AFFECTED AREAS.	New	3,936.00	1,312.00
5	TO CHECK WIRING SYSTEM.	New	134.64	134.64
6	TO DRILL HOLE AND INSTALL REVERSE SENSOR.	New	198.00	198.00
7	TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT.	New	594.00	594.00
8	TO RESET ECU AND REPROGRAMME.	New	198.00	198.00
9	TO REMOVE AND INSTALL REAR WINDSCREEN.	New	594.00	594.00
10	TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN.	New	480.00	480.00
11	TO SUPPLY REAR NUMBER PLATE.	New	80.00	0.00
Gross Labour Cost (\$\$)			11,266.64	5,244.64

Report was unsubmitted during this print-out.

< END OF ESTIMATES >