

ASS. REC. BY:

REF:

CS/LIP24070035/Kvh3e2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

XE 7463P

Policy No.

Claims No.

AVS24/2025

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8370k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PTR 921PP Yr Regn: 10.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 740Li c.c. 2998

Colour

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

43712 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 7T 220908 J44074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

245T 40R 20

R:

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

28/6/24

D.O.I.

3/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EN not ready

19/7 LT 2m 85900k Calm (red 13,030.45, 68%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fines

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Withair
 11 Pm @ 5900h
 Recovery After Rain

Make/Model: BMW 740Li

Engine/Chassis No.: WBA7T22090CJ44074

Date of accident: 28.06.24

Damaged area: O/S Rear

Date: 03/07/2024

Claim Type: TP

VRN: SJR9219P

5 x days

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>1664.50</i>	<i>Bu/om</i> 1	\$ 3,117.00	\$ 3,117.00 ✓
2	Rear bumper reinforcement	1 <i>R</i>	\$ 983.00	\$ 983.00 X
3	Rear bumper side carrier o/s	1 <i>lm</i>	\$ 263.00	\$ 263.00 X
4	Taillamp o/s <i>928</i>	<i>Brv</i> 1	\$ 1,309.00	\$ 1,309.00 —
5	Taillamp lower bracket o/s	<i>om</i> 1	\$ 161.00	\$ 161.00 —
6	Blind spot sensor o/s <i>1512.</i>	<i>pu</i> 1	\$ 1,995.00	\$ 1,995.00 ✓
7	Rear bumper side cover o/s	<i>lm</i> 1	\$ 485.00	\$ 485.00 X
8	Rear bumper side reflector o/s	<i>lm</i> 1	\$ 197.00	\$ 197.00 X
9	End panel	<i>R</i> 1	\$ 1,285.00	\$ 1,285.00 X
10	End panel top garnish	<i>lm</i> 1	\$ 562.00	\$ 562.00 X
11	Rear bumper lower cowl	<i>lm</i> 1	\$ 287.00	\$ 287.00 X
12	End panel top bracket	<i>R</i> 1	\$ 379.00	\$ 379.00 X
13	End panel support bracket	<i>R</i> 2	\$ 195.00	\$ 390.00 X
14	Rear bumper support bracket	<i>R</i> 1	\$ 484.00	\$ 484.00 X
15	Reverse sensor holder	<i>lm</i> 2	\$ 33.00	\$ 66.00 X
16	Bootlid kick sensor module	<i>lm</i> 1	\$ 831.00	\$ 831.00 X
17	Rear fender o/s <i>2180</i>	<i>R</i> 1	\$ 2,437.00	\$ 2,437.00 ✓
Subtotal				\$ 15,231.00
List discount				5.00%
Total				\$ 14,469.45

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper reverse sensor	<i>lm</i> 2	\$ 480.00	\$ 960.00 X
2	Rear bumper sensor seals	<i>lm</i> 2	\$ 28.00	\$ 56.00 X
3	Rear bumper clips	<i>lm</i> 12	\$ 5.50	\$ 66.00 ✓
4	End panel sealant	<i>lm</i> 1	\$ 120.00	\$ 120.00 X
5	End panel top garnish clips	<i>lm</i> 8	\$ 5.50	\$ 44.00 X
6	Rear bumper lower cowl clips	<i>lm</i> 18	\$ 5.50	\$ 99.00 X
7	Rear bumper lower side cowl clips	<i>lm</i> 12	\$ 5.50	\$ 66.00 X
8	Sundries	<i>lm</i> 1	\$ 50.00	\$ 50.00 X
Total				\$ 1,461.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	\$ 100.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	1	\$ ⁿⁿ 200.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To rust proof all affected portions after repair.	1	\$ 100.00
Total labour			\$ 3,000.00

700/

30/

X

800/

Estimate Grand Total	\$ 18,930.45
----------------------	--------------