

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Withheld
11/8/2024
Repair After Rain
6 days

Make/Model: BMW 740Li
Engine/Chassis No.: WBA7T22090CJ44074
Date of accident: 28.06.24
Damaged area: O/S Rear

Date: 03/07/2024
Claim Type: TP
VRN: SJR9219P

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>1664.50</i>	<i>Buclorn</i> 1	\$ 3,117.00	\$ 3,117.00
2	Rear bumper reinforcement	1 <i>RL</i>	\$ 983.00	\$ 983.00
3	Rear bumper side carrier o/s	1 <i>RL</i>	\$ 263.00	\$ 263.00
4	Taillamp o/s <i>928</i>	<i>RL</i> 1	\$ 1,309.00	\$ 1,309.00
5	Taillamp lower bracket o/s	<i>RL</i> 1	\$ 161.00	\$ 161.00
6	Blind spot sensor o/s <i>1512.</i>	<i>RL</i> 1	\$ 1,995.00	\$ 1,995.00
7	Rear bumper side cover o/s	<i>RL</i> 1	\$ 485.00	\$ 485.00
8	Rear bumper side reflector o/s	<i>RL</i> 1	\$ 197.00	\$ 197.00
9	End panel	<i>RL</i> 1	\$ 1,285.00	\$ 1,285.00
10	End panel top garnish	<i>RL</i> 1	\$ 562.00	\$ 562.00
11	Rear bumper lower cowl	<i>RL</i> 1	\$ 287.00	\$ 287.00
12	End panel top bracket	<i>RL</i> 1	\$ 379.00	\$ 379.00
13	End panel support bracket	<i>RL</i> 2	\$ 195.00	\$ 390.00
14	Rear bumper support bracket	<i>RL</i> 1	\$ 484.00	\$ 484.00
15	Reverse sensor holder	<i>RL</i> 2	\$ 33.00	\$ 66.00
16	Bootlid kick sensor module	<i>RL</i> 1	\$ 831.00	\$ 831.00
17	Rear fender o/s <i>2180</i>	<i>RL</i> 1	\$ 2,437.00	\$ 2,437.00
Subtotal				\$ 15,231.00
List discount				5.00%
Total				\$ 14,469.45

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper reverse sensor	<i>RL</i> 2	\$ 480.00	\$ 960.00
2	Rear bumper sensor seals	<i>RL</i> 2	\$ 28.00	\$ 56.00
3	Rear bumper clips	<i>RL</i> 12	\$ 5.50	\$ 66.00
4	End panel sealant	<i>RL</i> 1	\$ 120.00	\$ 120.00
5	End panel top garnish clips	<i>RL</i> 8	\$ 5.50	\$ 44.00
6	Rear bumper lower cowl clips	<i>RL</i> 18	\$ 5.50	\$ 99.00
7	Rear bumper lower side cowl clips	<i>RL</i> 12	\$ 5.50	\$ 66.00
8	Sundries	<i>RL</i> 1	\$ 50.00	\$ 50.00
Total				\$ 1,461.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.5	\$ 100.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	1	\$ <i>nn</i> 200.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To rust proof all affected portions after repair.	1	\$ 100.00
Total labour			\$ 3,000.00

700/

30/

X

800/

Estimate Grand Total	\$ 18,930.45
----------------------	--------------