



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4069R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LEFT A PILLAR (WCP)	BENT	480.00	480.00
1	WINDSCREEN (WCP)	CRACKED	450.00	450.00
1	LEFT SIDE MIRROR (WCP)	SCRATCHED	280.00	280.00
1	FRONT LEFT CORNER PANEL (WCP)	TO REPAIR SEE LABOUR	150.00	-
1	LEFT REAR MUD SHIELD (WCP)	DISTORTED	220.00	220.00
1	TRUNK BED LEFT LOCK (WCP)	TO REPAIR SEE LABOUR	90.00	-
1	REAR RAIN COVER CANVAS (WCP)	NOT INSURED	300.00	-
1	LEFT DOOR (WCP)	TO REPAIR SEE LABOUR	420.00	-
1	FRONT BUMPER (WCP)	DENTED/CUT	250.00	250.00
	COST PLUS 15%		396.00	252.00
			<b>3,036.00</b>	<b>1,932.00</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	WINDSCREEN SILICONE (SN)	NECESSARY	50.00	40.00
1	IU STICKER (SN)	NECESSARY	19.00	19.00
			<b>69.00</b>	<b>59.00</b>
<b><u>LABOUR</u></b>				
	REMOVE REFIT DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT LEFT CORNER PANEL, TRUNK BED LEFT LOCK AND LEFT DOOR.		880.00	600.00
	WINDSCREEN REMOVE AND INSTALL.		125.00	120.00
	PAINTWORK.		900.00	600.00
			<b>1,905.00</b>	<b>1,320.00</b>
<b>GRAND TOTAL</b>			<b>5,010.00</b>	<b>3,311.00</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,600.00</b>
<b>LESS EXCESS</b>			<b>-600.00</b>
<b>NETT LIABILITY</b>			<b>2,000.00</b>

Report Ref No. CS/LPC24120383/Kvh3m4(N)

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**