

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24120390/TQP3E2  
**Date:** 04/03/2025**REFERENCE**

Insured/Claimant:	TAN GEK MENG ( CHEN YIMING )	Policy No:	2070145666
Date of Loss:	23/12/2024	Nature of Claim:	OD Claim No: 9644705906SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SFT9117L</b>	Engine No:	CZDC04117
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF31M1001383
Reg. Date:	26/10/2020 (Man. Year: 2020)	Odometer:	57892 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	31,313.00	16,605.20	14,707.80	46.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,632.00	10,282.00	4,350.00	29.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>45,945.00</b>	<b>26,887.20</b>	<b>19,057.80</b>	<b>41.48</b>
<b>- Excess (\$\$)</b>	800.00	800.00	0.00	0.00
<b>(\$\$)</b>	45,145.00	26,087.20	19,057.80	42.21
<b>+ GST 9.00/9.00% (\$\$)</b>	4,063.05	2,347.85	1,715.20	42.21
<b>Nett Amount (\$\$)</b>	<b>49,208.05</b>	<b>28,435.05</b>	<b>20,773.00</b>	<b>42.21</b>

**INSPECTION**

Date of Assignment:	26/12/2024	
Date Inspected:	27/12/2024	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,594.00 FS	*2,074.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	O/S Not Necessary/N/S Deformed	148.00 FS	*59.04 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	272.00 FS	*217.20 FS
4	1		*FRONT BUMPER GRILLE - LH / RH	O/S Not Necessary/N/S Cracked	278.00 FS	*110.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Deformed	238.00 FS	*190.00 FS
6	1		*FRONT BUMPER SPOILER	Deformed	479.00 FS	*382.80 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Deformed	192.00 FS	*153.60 FS
8	1		*RADIATOR GRILLE	Cut	1,795.00 FS	*1,436.00 FS
9	1		*RADIATOR GRILLE STRIKER PLATE	Distorted	303.00 FS	*242.40 FS
10	1		*FRONT BUMPER LOWER GRILLE COVER PLATE	Missing	65.00 FS	*51.60 FS
11	1		*FRONT BUMPER GUIDE SECTION - LH	Deformed	49.00 FS	*38.56 FS
12	1		*FRONT BUMPER TOP COVER	Deformed	154.00 FS	*123.20 FS
13	1		*CAUTION SIGN STICKER	Necessary	25.00 FS	*19.44 FS
14	1		*OIL COMPLY WITH VW STANDARD STICKER	Necessary	25.00 FS	*19.44 FS
15	1		*AIR CONDITIONER STICKER	Necessary	10.00 FS	*7.52 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	1,116.00 FS	*892.80 FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	129.00 FS	*- FS
18	1		*FRONT PARKING AID SENSOR - LH	Not Working	286.00 FS	*228.80 FS
19	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
20	1		*SET FRONT BUMPER WIRING	Not Necessary	804.00 FS	*- FS
21	1		*FRONT FENDER - LH	Bent	1,537.00 FS	*1,229.60 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	74.00 FS	*- FS
23	1		*FRONT FENDER BRACE - LH	Bent	127.00 FS	*101.60 FS
24	1		*FRONT FENDER BRACKET - LH	Bent	58.00 FS	*46.32 FS
25	1		*FRONT FENDER DAMPING - LH UPPER	Not Necessary	40.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER - LH	Torn	289.00 FS	*231.20 FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
28	1		*FRONT WHEEL HOUSING LINER COVER - LH	Torn	20.00 FS	*15.68 FS
29	2		*FRONT WHEEL COVER - LH / RH	Cut	636.00 FS	*508.00 FS
30	1		*HEADLIGHT - LH	Cracked	6,696.00 FS	*5,356.80 FS
31	1		*HEADLIGHT POWER MODULE	Not Necessary	904.00 FS	*- FS
32	2		*HEADLIGHT COMPENSATING PIECE	Necessary	100.00 FS	*39.84 FS
33	1		*LIFT CYLINDER - LH	Cracked	244.00 FS	*195.20 FS
34	1		*LIFT CYLINDER HOSE	Not Necessary	102.00 FS	*- FS
35	1		*HEADLIGHT MOUNTING - LH	Cracked	147.00 FS	*117.60 FS
36	1		*LOCK CARRIER	Cracked	1,591.00 FS	*1,272.80 FS
37	1		*RADIATOR AIR GUIDE - LH	Deformed	50.00 FS	*39.92 FS
38	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Distorted	112.00 FS	*44.64 FS
39	1		*READY-MIX COOLANT (6PCS)	Necessary	332.00 FS	*265.44 FS
40	1		*HORN HIGH TONE - LH	Distorted	162.00 FS	*129.60 FS
41	1		*HORN BRACKET - LH	Bent	28.00 FS	*21.68 FS
42	1		*FRONT WINDSCREEN WASH WATER RESERVOIR	Deformed	269.00 FS	*214.80 FS
43	1		*FRONT WINDSCREEN WASHER END CAP	Not Necessary	26.00 FS	*- FS
44	1		*FRONT WINDSCREEN WASHER HOSE	Not Necessary	30.00 FS	*- FS
45	1		*FRONT WINDSCREEN WASHER SYSTEM PUMP	Cracked	147.00 FS	*117.60 FS
46	1		*FRONT WINDSCREEN WASHER PUMP SEAL	Necessary	10.00 FS	*7.60 FS
47	1		*FRONT DOOR COVER - LH	Not Necessary	318.00 FS	*- FS
48	1		*HEADLIGHT - RH	Not Necessary	6,696.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*LIFT CYLINDER - RH	Not Necessary	244.00 FS	*- FS
50	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
51	1		*SUNDRIES	Necessary	800.00 FS	*39.20 FS
52	1		*RHS HEADLIGHT MOUNTING (SUPPLEMENTARY)	Cracked	147.00 FS	*117.60 FS
53	1		*BONNET RELEASE ELEMENT (SUPPLEMENTARY)	Distorted	73.00 FS	*57.76 FS
54	1		*SOCKET CONNETOR (SUPPLEMENTARY)	Cracked	28.00 FS	*21.68 FS
55	1		*WINDSCREEN WASHER PUMP SEAL (SUPPLEMENTARY)	Necessary	71.00 FS	*56.32 FS
56	1		*INTAKE AIR GUIDE LOWER (SUPPLEMENTARY)	Deformed	61.00 FS	*48.72 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** 31,313.00 16,605.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE	New	800.00	800.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESURRISE COOLING SYSTEM	New	1,800.00	1,800.00
5	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,500.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,700.00	1,650.00
8	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	480.00
9	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS	New	800.00	800.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (S\$)</b>			<b>14,632.00</b>	<b>10,282.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >