

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24120393/AVP3E2
Date: 10/03/2025

REFERENCE			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001446746
Claimant Vehicle No :	SNP2499G	Insured Vehicle No :	SLF3868U
Date of Loss:	11/12/2024	Nature of Claim:	TP
		Claim No:	385864

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNP2499G	Engine No:	FA24CN25232
Make & Model:	SUBARU WRX WAGON, 2.4 EYESIGHT AWD CVT (A)	Chassis No:	JF1VBHK85PG007011
Reg. Date:	26/01/2024 (Man. Year: 2023)	Odometer:	20119 km
Colour:	Black		
Engine Capacity:	2387 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Parts : 1050.60			
20%	840.00	Repairer's	Adjuster's	Difference	Diff %
Parts	450.00	3,800.74	3,731.90	68.84	1.81
Miscellaneous Items	1290.00	0.00	0.00	0.00	
Labour		1,800.00	450.00	1,350.00	75.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross Total (S\$)		5,600.74	4,181.90	1,418.84	25.33
Approved Total (Overridden) (S\$)			3,300.00		
Nett Amount (S\$)		5,600.74	3,300.00	2,300.74	41.08

INSPECTION

Date of Assignment:	26/12/2024		
Date Inspected:	30/12/2024	Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Mar 2025)	
Parts:	N/A	SUBARU WRX WAGON 2.4 EYESIGHT AWD CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNP2499G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	854.16 FL	*854.16 FL
2	1		*FRONT BUMPER RH HOLDER	Cut	78.00 FL	*78.00 FL
3	1		*FRONT BUMPER RH SIDE GARNISH	Cut	46.44 FL	*46.44 FL
4	1		*FRONT BUMPER LOWER SIDE GARNISH	Not Necessary	86.04 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Necessary	72.00 FL	*72.00 FL
6	1		*FRONT RH HEAD LAMP	Cut	3,614.28 FL	*3,614.28 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,750.92	4,664.88
- List Item Discount on L Items 20.00/20.00% (S\$)	950.18	932.98
Total Parts (S\$)	3,800.74	3,731.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT	New	1,000.00	250.00
2	RESPRAY PAINTING	New	800.00	200.00
Gross Labour Cost (S\$)			1,800.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >