



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 3043X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WINDSCREEN (WCP)	CRACKED	550.00	550.00
1	FRONT WINDSCREEN RUBBER (WCP)	NECESSARY	220.00	220.00
1	FRONT DOOR LH (WCP)	BENT	480.00	480.00
1	FRONT DOOR LOWER GARNISH LH (WCP)	CUT	60.00	60.00
1	FRONT DOOR OUTER HANDLE LH (WCP)	CUT	65.00	55.00
1	FRONT DOOR MIRROR LH (BIG) (WCP)	CUT	25.00	25.00
1	FRONT DOOR MIRROR LH (SMALL) (WCP)	CUT	50.00	40.00
1	FRONT SIGNAL LAMP LH (WCP)	CRACKED	180.00	175.00
1	FRONT HEADLAMP SIDE COVER LH (WCP)	CRACKED	125.00	125.00
1	BLUETEC STICKER LH (WCP)	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE LH (WCP)	SERVICEABLE	100.00	-
1	REAR CARRIAGE DROP DOOR STOPPER LH (WCP)	SERVICEABLE	5.00	-
1	STEP GARNISH LH (OUTER) (WCP)	MTG CRACKED	350.00	350.00
3	FUEL INJECTORS @\$390.00 (WCP)	SERVICEABLE	1,170.00	-
1	FUEL INJECTOR LINE (WCP)	SERVICEABLE	155.00	-
1	FRONT DOOR GLASS CHANNEL LH (WCP) (ADDITIONAL)	DENTED	135.00	135.00
1	FRONT SIDE PANEL RUBBER SEAL (WCP) (ADDITIONAL)	NECESSARY	28.00	28.00
1	FUEL INJECTOR (WCP) (ADDITIONAL) (SERVICEABLE)	NOT CONSISTENT WITH THE IMPACT	390.00	-
	COST PLUS 10%		412.80	228.30
			4,540.80	2,511.30
1	WARNING DECAL (SN)	NECESSARY	40.00	40.00
	COST PLUS 10%		4.00	-
			44.00	40.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR CARRIAGE DROP DOOR C/W BOARD LH (SN)	BENT	800.00	800.00
1	REAR CARRIAGE DROP DOOR C/W BOARD RH (SN)	BENT	800.00	800.00
1	REAR CARRIAGE DROP DOOR RAIL LH (SN)	BENT/DISTORTED	650.00	650.00
1	REAR CARRIAGE DROP DOOR RAIL RH (SN)	BENT	650.00	650.00

Report Ref No. CS/UOI24120394/Knp3m4(N)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CARRIAGE DROP DOOR HANDLE LH (FRONT) (SN)	DENTED	40.00	40.00
1	IU BRACKET (SN)	NECESSARY	15.00	15.00
1	LITRE ENGINE OIL (XHP ESP) (SN)	NECESSARY	16.00	16.00
			2,971.00	2,971.00
	<b><u>LABOUR</u></b>			
	TOWING FEE.		60.00	60.00
	TO DISMANTLE+RENEW FRONT WINDSCREEN.		180.00	120.00
	TO REMOVE+REFIX/RENEW FUEL INJECTORS+FUEL INJECTOR LINE, TO REMOVE ENGINE OIL (ACCUMULATED ABOVE PISTONS), ETC.		200.00	160.00
	TO KNOCK DENTS ON FRONT WINDSCREEN PILLAR LH, 'B' PILLAR LH, CABIN ROOF SIDE PANEL LH AND RENEW PARTS.		900.00	800.00
	TO SPRAY PAINT.		1,200.00	1,100.00
			2,540.00	2,240.00
<b>GRAND TOTAL</b>			<b>10,095.80</b>	<b>7,762.30</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>7,762.30</b>
<b>LESS EXCESS</b>			<b>-600.00</b>
<b>NETT LIABILITY</b>			<b>7,162.30</b>

Report Ref No. CS/UOI24120394/Knp3m4(N)

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.