1/14/25, 3:45 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24120395/ENP3M4

2ZR2R57585

389412 km

JTDKB3FU903096790

Date: 14/01/2025

Engine No:

Chassis No:

Odometer:

**REFERENCE** 

Handling Insurer: **ECICS Limited** 

Policy No:

**Claimant Vehicle** No:

SHD4991Y

Insured Vehicle No: SLB8159X

Date of Loss: 19/12/2024 Nature of Claim: TP Claim No: DMPC2401758H/02/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SHD4991Y** Reg No:

TOYOTA PRIUS, 1.8 5DR HATCHBACK (AUTO) Make & Model:

(2WD) (A)

Reg. Date:

21/07/2022 (Man. Year: 2022) Colour:

Blue 1798 cc

**Engine Capacity:** 

Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 195/65R15 Rear Tyre Size: Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm Rear Right Side: Giti 6 mm Front Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,965.92	550.71	2,415.21	81.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	680.00	80.00	10.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,725.92	1,230.71	2,495.21	66.97
+ GST 9.00/9.00% (S\$)	335.33	110.76	224.57	66.97
Nett Amount (S\$)	4,061.25	1,341.47	2,719.78	66.97

**INSPECTION** 

Date Inspected:

Date of Assignment: 26/12/2024

COMFORTDELGRO ENGINEERING PTE LTD

(LOYANG) 26/12/2024 Inspected At:

59 LOYANG DRIVE SINGAPORE 508969

Estimated Period of Repair:

Adjuster: **CHEN TSUE YEE** Manager: **HUEY YON** 

2.0 days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Yes

### REPAIR DETAILS

		_			
$\mathbf{L}$	$\sim$	-	2	$\overline{}$	$\overline{}$
$\overline{}$	_	_	-		_
		$\sim$	re	 u	u

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2025)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (AUTO)(2WD) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD4991Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Broken	586.18 FL	*586.18 FL
2	10	*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1	*HEADLAMP RH	Not Necessary	2,735.28 FL	*- FL
4	1	*FRT BUMPER SPONGE	Not Necessary	78.80 FL	*- FL
5	1	*FRT BUMPER LOWER GRILLE	Not Necessary	301.90 FL	*- FL
6	1	*FRT BUMPER SIDE GRILLE RH	Cut	148.10 FL	*148.10 FL
7 E=Ers	1 anchise part. L=ListIte	*FRT BUMPER SIDE BRACKET RH	Not Necessary	82.30 FL	*- FL
1 -1 16	anomise part. L-Listite	iliDisc.	Sub Total (S\$)	3,954.56	734.28
		- List Item Discount o	on L Items 25.00/25.00% (S\$)	988.64	183.57
			Total Parts (S\$)	2,965.92	550.71
		Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	CHECK ALL LIGHTING / WIRING	New	60.00	20.00
	Gross Labour Cost (S\$)		760.00	680.00
	Report w	as unsubmitted during this print-out.		

< END OF ESTIMATES >