

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120397/AUA3Q2**Date:** 18/02/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220045741
Claimant Vehicle No :	SDW68L	Insured Vehicle No :	EF45E
Date of Loss:	24/12/2024	Nature of Claim:	TP
		Claim No:	1804045690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW68L	Engine No:	CVK088017
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Chassis No:	WAUZZZF50KA078955
Reg. Date:	30/09/2019 (Man. Year: 2019)	Odometer:	84217 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,495.00	13,731.00	6,764.00	33.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,572.00	3,122.00	2,450.00	43.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	26,067.00	16,853.00	9,214.00	35.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/12/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI)
Date Inspected:	27/12/2024		55 Ubi Road 1
Estimated Period of Repair:	4.0 days		Singapore 408699

Adjuster: ADRIAN LING**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,802.00 FS	*2,802.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	458.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	45.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	286.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE LH	Not Necessary	71.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	598.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	46.00 FS	*- FS
8	1		*FRONT BUMPER TOP BRACKET	Not Necessary	173.00 FS	*- FS
9	1		*FRONT PARKING AID SENSOR LH OUTER	Not Necessary	286.00 FS	*- FS
10	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
11	1		*HEADLIGHT LH	Cut	9,447.00 FS	*9,447.00 FS
12	2		*HEADLIGHT COMPENSATING PIECE	Not Necessary	100.00 FS	*- FS
13	1		*LIFT CYLINDER LH	Not Necessary	238.00 FS	*- FS
14	1		*LIFT CYLINDER BRACKET LH	Not Necessary	19.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	110.00 FS	*- FS
16	1		*FRONT FENDER LH	Dented	1,264.00 FS	*1,264.00 FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
18	1		*FRONT FENDER CLOSING ELEMENT -LH	*Check	92.00 FS	*- FS
19	1		*FRONT FENDER BRACKET -LH FRONT	*Check	45.00 FS	*- FS
20	1		*FRONT FENDER RIVET (6 PCS)	Necessary	26.00 FS	*26.00 FS
21	1		*FRONT FENDER BRACKET -LH REAR	Not Necessary	73.00 FS	*- FS
22	1		*FRONT FENDER BRACKET -LH CENTER	Not Necessary	56.00 FS	*- FS
23	1		*FRONT FENDER BRACE LH	*Check	177.00 FS	*- FS
24	1		*FRONT FENDER LOWER BRACKET LH	Not Necessary	61.00 FS	*- FS
25	1		*FRONT FENDER CHROME TRIM -LH	Necessary	192.00 FS	*192.00 FS
26	1		*FRONT FENDER LEDGE COVER LH INNER	Not Necessary	64.00 FS	*- FS
27	1		*FRONT FENDER LEDGE COVER LH OUTER LONG	Not Necessary	45.00 FS	*- FS
28	1		*FRONT FENDER LEDGE COVER LH OUTER SHORT	Not Necessary	20.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	332.00 FS	*- FS
30	1		*FRONT WHEEL SPOILER	Not Necessary	92.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
32	1		*SIDE MEMBER TRIM ATTACHMENT PARTS	Not Necessary	153.00 FS	*- FS
33	1		*SIDE MEMBER TRIM ADHESIVE TAPES	Not Necessary	233.00 FS	*- FS
34	1		*FRONT ALUMINIUM RIM LH	Not Necessary	2,123.00 FS	*- FS
35	1		*FRONT ALUMINIUM RIM RUBBER VALVE -LH	Not Necessary	5.00 FS	*- FS
36	1		*SUNDRIES	*Check	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,495.00 13,731.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT HORNS OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			5,572.00	3,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >