

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24120400/APA3Q2**Date:** 30/07/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900170778
Claimant Vehicle No :	SMA1634E	Insured Vehicle No :	SMP5412Z
Date of Loss:	20/12/2024	Nature of Claim:	TP
		Claim No:	2268488276SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1634E		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NR5218631
Reg. Date:	30/05/2018 (Man. Year: 2018)	Chassis No:	MR2B23F3401121929
Colour:	Silver	Odometer:	236834 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,598.60	5,774.31	2,824.29	32.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,840.00	450.00	19.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,888.60	7,614.31	3,274.29	30.07
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	10,888.60	6,100.00	4,788.60	43.98
+ GST 9.00/9.00% (S\$)	979.97	549.00	430.97	43.98
Nett Amount (S\$)	11,868.57	6,649.00	5,219.57	43.98
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		7,291.18		

INSPECTION

Date of Assignment:	26/12/2024	
Date Inspected:	26/12/2024 Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,327.95 FL	*1,327.95 FL
2	1		*BOOT LID LOGO	Necessary	66.90 FL	*66.90 FL
3	1		*BOOT LID VIOS EMBLEM	Necessary	58.65 FL	*58.65 FL
4	1		*BOOT LID E EMBLEM	Necessary	49.20 FL	*49.20 FL
5	1		*BOOT LID LAMP RH	Not Necessary	412.24 FL	*- FL
6	1		*BOOT LID LAMP LH	Not Necessary	412.24 FL	*- FL
7	1		*BOOT LID LOCK	Damaged	602.88 FL	*560.00 FL
8	1		*BOOT LID LOCK CHECKER	Not Necessary	49.95 FL	*- FL
9	1		*BOOT LID RUBBER	Cut	264.76 FL	*264.76 FL
10	1		*BOOT LID TRIM	Not Necessary	491.37 FL	*- FL
11	1		*REAR PANEL	Dented	1,236.60 FL	*995.00 FL
12	1		*REAR PANEL TRIM	Deformed	420.52 FL	*390.00 FL
13	1		*TAIL LAMP RH	Cut	955.49 FL	*780.00 FL
14	1		*TAIL LAMP LH	Cut	955.49 FL	*780.00 FL
15	1		*REAR BUMPER	Deformed	891.62 FL	*891.62 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	558.52 FL	*420.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Cracked	517.90 FL	*330.00 FL
18	1		*REAR BUMPER SMALL RETAINER	Not Necessary	199.26 FL	*- FL
19	1		*REAR BUMPER REFLECTOR RH	Not Necessary	141.59 FL	*- FL
20	1		*ANTENNA SENSOR	Cracked	285.00 FL	*285.00 FL
21	1		*BOOT LID 609 STICKER	Necessary	35.00 FS	*35.00 FS
22	1		*SET BOOT LID TRIM CLIPS	Not Necessary	40.00 FS	*- FS
23	1		*SET REAR PANEL TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
24	1		*REAR FENDER STICKER RH	Not Necessary	290.00 FS	*- FS
25	1		*REAR FENDER STICKER LH	Not Necessary	290.00 FS	*- FS
26	2		*L PLATE BRACKET	Necessary	140.00 FS	*90.00 FS
27	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
28	1		*REAR BUMPER STICKER	Necessary	290.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,073.13	7,574.08
- List Item Discount on L Items 25.00/25.00% (\$)	2,474.53	1,799.77
Total Parts (\$)	8,598.60	5,774.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKERS	New	80.00	50.00
3	TO SPRAY AND SEALANT	New	80.00	80.00
4	TO REFIX REAR INNER TRIM	New	80.00	80.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	1,000.00	800.00
6	TO SPRAY PAINTING DAMAGED PORTION ,INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE SAND PARTS PRIMER POLISHING COMPOUND AND CHEMICAL ETC	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,290.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >